



Sketch No 1 1/2

See sketch no. 1, by W.S. Mabry.

"Working Plat" showing the beginning & calls for adjacent surveys, and original corner locations

See sketch in Box 21876 for re-survey &c 12-29-1913. E. von Rosenberg Chief Draftsman

See letter to H. D. Twichell State Surveyor at Herford Tex 4/3/90 by Robison Vol. 683 p-52