

Estes SR  
B1K43-4

566

File No.

Sketch File 20

ANDREWS

(Transferred from Rld. Sk. 17, 10-9-1993, d.) County

Filed

Feb. 28

1935

GARRY MAURO, Com'r

By Douglas Howard (10-9-1993, d.)

ROBT. E. ESTES  
LICENSED LAND SURVEYOR

MIDLAND, TEXAS

February 26, 1935

Hon J.H. Walker,  
Commr Gen'l Land Office,  
Austin, Texas

Dear Sir:

Herewith are the subdivision field notes for section 10. Blk. A43 Andrews County also section No. 1. same Block.

The field notes for section 6. is correct, and you are authorized to change the call on the sketch from N.15°47'W. to N.16°01'W. this is the second call in the field notes. I am returning the field notes without change.

In making the survey of Blocks A43 and A44 Public school land, I find the original N.E. corner of Block A44, and also the original S.W. corner. I find the N.W. corner of Block A43 (orig) I also find the S.W. corner of Blk. A43 with the bearings as described and at the S.W. cor of section 22 Blk. A43 I find the original corner

On the East line of section 10. Blk. A43 I find and check the calls in the original field notes for the old road and the basin,

From these determined points I construct the lines of the surveys for which I made the field notes. The original N.E. cor of sec 6. Blk. A44, and the original N.E. cor of section No. 1. Blk. A43 I did not find, as a County road passes over both these corners, but from former work I know the position of these corners. The direction of the lines in this survey are referred to a true meridian passing thru the N.E. cor of section No. 1. Blk. A44.

The total distances between the Block lines are prorated amongst the sections, except where original corners or calls are found, then they control. It will be seen from the sketch that the North lines of Blocks A44 and A43 are slightly longer than the South lines. The length of the West line of Blk. A43 is a few verses shorter than the East line. The north South distance of the sections vary along the East line of Blk. A43. This is on account of the call for the old road and the Basin which I find as called for on the East line of section 10.

The above is in conformity to the requirements as set out in your letter of February 8.

Giles:eb

encs

F-76519-20-13-80632-3

97651-2-117050-117180

131571-137532-344-5-6-7-8-9 -&

76519

117180

RECEIVED

FEB 28 1935

REFERRED TO MAP

Very truly yours

Robt E Estes

Licensed Land Surveyor  
Midland, Texas

COUNTER #  
12916

Andrews Co -

For use in connection  
with letter only -

COUNTER # 12917

PUBLIC School -

BLK. 41

B 42

B 43

B 44.

conflicting  
Area - if line is straight

BLK P.

BLK 11

BLK 10-

BLK 9.

Univ

Position of FF Line  
as it is on the ground

BLK 1.

R.M.M.K.O.  
R.M.M.K.P. on  
beginning Cor.  
of BLK 1.

Univ. B 2 -

R.M.M.K.N.

R.M.M.K.L.

G.M.M.B & A.

TSP No 2. North -

= See large sketch =

File No. Sketch File 20  
ANDREWS

Transferred from RD Sk. 17 10-9-1993 (h)

Filed

Feb. 28

GARRY MAURO, Com'r

By Douglas Howard (10-9-1993 h)

DOVER  
LAND  
SURVEY  
CO.  
FEDERAL LAND  
MOBIL

Position of FF Line  
if projected straight  
at this point.

FF Line swing to left  
at this point.

North Line BLK 40 & 41 -

ROBT. E. ESTES

LICENSED LAND SURVEYOR

MIDLAND, TEXAS

With  
Andreas  
Co.  
RLO SK 17

#17

PLACE WITH ANDREWS CO

RLO SK NO 17

COUNTER # 12918