

EXPLANATION.

Sur.34-2. - C.C.S. D. & R.G.N.G. Ry. Co.,
Cert. 1152.

East Part

Evidence of a Prairie Fire that occurred in this part of Brooks county, since 1935, is plainly to be seen, pasture fences were burned down as can be seen by charred remains of fence posts, and in mesquite timber, and a corner, a pointed stake, set by J.L.Dellis in 1935, and no doubt other corners marked with stakes or posts were also burned, I found the burned stump of the Dellis stake in the ground, by his bearing call, and no doubt older corners in this vicinity were destroyed.

On the lines of the East part of original survey No. 34, three original corners were found.

The S W corner of the East part and the upper S E corner of the West part on the North line of the E.Martinez grant, "La Noria de Tio Ayala", this corner was set or found by J.L.Dellis in 1935, when he surveyed the West part of this survey for patent, and is still on the ground with bearings.

The S W corner of C.& M.Ry.Co., Sur.353 and S E corner of Sur.354 by same certificate.

The S E corner of said Sur.353.

These corners are fully described in my field notes.

The S E and N E corner posts of Sur.34, are not on the ground, and were probably burned in the fire above mentioned, as was the fence line on the North line of the E.Martinez grant.

At the N E cor of Sur.34, I could locate some Live Oak trees, about course and distance as called in the 2nd call of Sur.34, but I could not find any marks on any of them.

Corrected Sur.34 was made by T.A.Chamberlain in April, 1910, and while making this survey of the East part, after leaving the S E corner of Sur.353, I followed his calls for course and distance as closely as possible.

Harvey E. ...
Licensed Land Surveyor

RECEIVED

APR 26 1940

REFERRED TO MAP

File No. 4

Brooks County
By Hays Dix
8 miles S 12 E. from Falfurrias

Filed May 1, 1940

BASCOM GILES, Com'r

H. U. von Rosenberg
File Clerk

Counter 16550

Licensed Land Surveyor
Hays Dix

course and distance as closely as possible.

leaving the S E corner of Sur. 353. I followed his calls for 1910, and while making this survey of the East Part, after corrected Sur. 34 was made by T. A. Chamberlain in April, then.

call of Sur. 34, but I could not find any marks on any of Oak trees, about course and distance as called in the 2nd E. Merittiner Grant.

At the N E cor of Sur. 34, I could locate some live mentioned, as was the fence line on the North line of the the ground, and were probably burned in the fire above.

The S E and N E corner posts of Sur. 34, are not on these corners are fully described in my field notes.

The S E corner of said Sur. 353 of Sur. 34 by same certificate.

The S W corner of C. & M. Ry. Co., Sur. 353 and S E corner with bearings.

part of this survey for patent, and is still on the ground found by J. L. DeJia in 1933, when he surveyed the West Grant, "La Norris de Tho Ayala", this corner was set on corner of the West part on the North line of the E. Merittiner

The S W corner of the East Part and the upper S E 34, three original corners were found.

On the lines of the East Part of original survey No. - were in this vicinity were destroyed.

the ground, by his bearing call, and no doubt older confirmed. I found the burned stump of the DeJia stake in doubt other corners marked with stakes or posts were also - near, a pointed stake, set by J. L. DeJia in 1933, and no remains of fence posts, and in meadow timber, and a corner fence were burned down as can be seen by charred of Brooks county, since 1933, is plainly to be seen. Passage of a Prairie Fire that occurred in this part

East Part

Cont. 1125

Sur. 34-S. - C. C. 2. D. A. R. E. N. G. R. Co.

EXPLANATION.

State

770