

2.

Fisher Co
1/1/1902

Filed in Genl. Tol Office
2/26/1902

Wise
NS Bonners SK of Surs
Ground Sec 107. EIK 1. H &
TC RICH & CO.

RR

200

230

210

200

211

200

207

210

counter 22649

I, J. S. Bonner County Surveyor Fisher County Tex. do hereby certify that I actually made the survey as indicated by the line and find as shown see in this plat. The call for S 41° corner of Sec. 107 brings it out of harmony with its NW corner. Both old corners easily identified by 100 varas, and causes a shortage in the line from it to the NW corner of Sec. 101 where we find a original corner easily identified. one dead stump about 3 feet high plainly marked, the other a stump that fits the call. What must I do with the shortages place it all to one section or divide it equally? I believe the call ought to be 25° 20' N 75° E instead of 125° 20' N 75° E. At the NW corner of 107 I find a call out of harmony the call is 71 1/2° 20' N 15° 41' W and the East line of Sec. 101 only 1850 varas. To make the call 21 1/2° 20' N 15° 41' W instead of 71 1/2° 20' N 15° 41' W will adjust the cramp, each section then will have 1900 varas. The records in my office have been badly kept, but I find errors on the ground. In making this survey I made connection with six old corners according to Bagley's records. I will give it your earliest I make this report to you hoping you will do in such actual difficulties attention and instruct me what to do in such actual difficulties. Yours Truly J. S. Bonner County Surveyor

P.S. I find an excess of 10 varas to the mile from the SW corner of Sec. 90 to the NW corner of Sec. 101 what must I do with it? The red circles indicate old corners that can be easily identified. J. S. Bonner County Surveyor