

Dear Sir.

Your favor of 23rd ult. was received. Mch. 1/77

Part of the error in measuring Hawk River appears to have been caused by the different variation used. — The Surveys on the northside are run with $9\frac{3}{4}^{\circ}$ to 10° — Those on the Southside with $10\frac{1}{2}^{\circ}$ to $10\frac{3}{4}^{\circ}$. (The old Survey is for N 14.)

In the mid part of the County, the N. W. Cor. of N^o 298. in Cameron is about opposite the S. W. Cor. of N^o 700. — The middle North Corner of two 32000 Surveys made last year on Southbank of Hawk is about half a mile below mouth of Leon Creek (on Northside). — The middle Corner of two abandoned Prescriptions on Southbank is opposite mouth of Saline on Northbank.

The connection of a 640 ac. Survey made Spring last year at mouth of Salt Creek with James Poy^{connected} will with Salt Creek & James River Plat will give the correct situation of the latter on map. If you give no correct measurement between corners on North & Southbank of Hawk. Respectfully Wm. Robertson
counter 30682

3^a

H. R. von Biberstein's Letter - Apr.

Dated Mar. 1st 1877

about summations
between survey
or Mason & K. file
Iland river. The con-
sult give correct mea-
sures. I believe the amount
of proper comparison
of the two summations
about triangulation