



The State of Texas, H. B. Brinton, Surveyor of Mason County, hereby certifies that the following discrepancies were found with former statements.

South line of No 22, is 2580 on - inst. of 2550 on. - South line of No 7 is 2630 on. inst. of 2550 on
 South line of No 8 is 2684 on - inst. of 2550 on. - North line of No 8 is 29950 inst. of 9824
 S. E. Cor. of No 118 is 980 on. inst. of 950 on. - and the S. E. Cor. is South 420 on. West 150 on
 from S. W. Cor. of No 118, inst. of South 340 on. - Survey No 118 does not close for 100 on. according to
 Field notes, and for 130 on. on the ground, in consequence the closing North line had to be run
 North 2° 15' W. inst. of North. - It appears that the following named Surveys had not
 been actually run out, because after a minute search no lines or corners could be found
 Nos 118, 119, 120, 121, 122, 123. - When established the corners and lines of No 118 from the
 S. W. Cor. of No 22, S. E. Cor. of No 7, S. W. Cor. of No 24, all of which corners agreed with description.
 The corners and lines of No 124 were established, from its S. E. Cor., which corresponds with
 description and connects correctly with Survey's further east and south.

The missing corners of Nos 124 and 118 being established, the lines were run from
 from the S. W. Cor. of No 124, and the line, a b, was found to be 3240 inst. of 3000
 line, b c, was found to be 1249 inst. of 1000 in connecting with supposed S. W. Cor. of No 119.

March 14, 1876 Counter 30691 H. B. Brinton, Sur. Mason County

Mason Co.

No. 8

Arvon Bibersteins Sketch
About 18 mi S35° E. of Mason.

counter 30692