



General Land Office.

State of Texas.

Austin.

7/28/02.

CHARLES ROGAN, COMMISSIONER.
J. J. TERRELL, CHIEF CLERK.

Mr Chas. B Mc Lain,
Dep. Sur. Oldham Land Dist.,
Tascosa, Texas.

Dear sir,---Upon examining the field notes of the vacant territory in Moore County surveyed by you I find errors as follows:

Survey No. 10, Blk. M 1, R. W. Eldridge, recorded in Bk. B pg. 237, field notes do not close, error in departure 690 vrs. evidently in 3rd course West, the total length of line is omitted.

Sur. 15, Blk. M 1, O.E. Gober, Bk. A pg. 6, field notes do not close, error in Lat. 74 vrs.

Sur. No. 21, Blk. M 2, A.O. Campbell, Bk. A, pg. 12, f/notes do not close, error in Lat 17 vrs. and the course West 39' S should be 89 22' W.

Sur. No. 22, Blk. M 2, A.O. Campbell, Bk. A pg. 11, f/notes do not

counter 31939



General Land Office.

State of Texas.

Austin.

CHARLES ROGAN, COMMISSIONER.
J. J. TERRELL, CHIEF CLERK.

C.B. Mc Lain Pg. 2.

close, error in Lat. 18 vrs. and the 2nd course West 38' S should read S 89 22' W .

Sur. No. 23, blk. M2, A.O. Campbell, Bk. A, pg. 14, f/notes do not close , error in Lat. 8 1/2 vrs. evidently the length of the 3rd course N 1780 vrs. should be 1788 1/2 vrs. the same as the length of the first course; the second and fourth courses should read S 89 22' W and N 89 22' E.

Sur. No. 22, Blk. M 1, B.C. Campbell, Bk. A pg. 4, contains 644.38 instead of 640 acres, correction or explanation required.

Survey No. 18, Blk. M 1, J.B. Wheatley, Bk. A pg. 96, contains 661.8 acres instead of 640 acres, correction or explanation required.

The field notes of the following surveys are not written according to our custom of land surveying, for instance, you say thence West



General Land Office.

State of Texas.

Austin.

CHARLES ROGAN, COMMISSIONER.
J. J. TERRELL, CHIEF CLERK.

C.B. Mc Lain Pg. 3.

38' S and East 38' N, this should read S 89 22' W and N 89 22' E.

Again East 4 32' S should read S 85 28' E.

Sur. No.	Blk.	M1	Bk.	A	Pg.	27
23		Do.		Do.		3
24		Do.		Do.		16
25		Do.		Do.		2
2	"	Blk M2	"	Blk B		255
3		Do		Do		256
4		Do		Do		257
5		Do	"	A		22
8		Do		Do		29
9		Do		Do		30
10		Do		Do		31
11		Do		Do		32
12		Do		Do		19
13		Do.		Do		18
14		Do		Do		17
15		Do		Do		15
16		Do		Do		10
17		Do		Do		9
18		Do		Do		8
19		Do		Do		7
24		Do.	"	B		83



General Land Office.

State of Texas.

Austin.

CHARLES ROGAN, COMMISSIONER.
J. J. TERRELL, CHIEF CLERK.

C.B. Mc Laim Pg. No. 4.

Please correct your records according~~x~~ and notify this office.

You failed to return a certified sketch of these surveys showing the connections between Blks. No. 44 and Blk. 3 T as found on the ground.

With regard to the files that we claim you do not write the field notes according to our custom, you will please make necessary corrections and let us have filed notes prepared in accordance with the custom which this office follows in the matter surveying lands.

Very respectfully,

Mac Inerney.

(See orig by E. T. R. R.,
attached)

Chief Clerk.

Handwritten notes:
Amount of money of 100 of 1/4 of 1/4
1885
Office of the Chief Clerk

Office letter to Chas B, G,
McLain, in re to vacant lands
Dated July 28, 1902.

Moore Co

RECEIVED
JUL 30 1902

Moore Co

Moore Co



counter 31943

Moore Co. St. File #6

Mr. Chas B. Mc Lain
Dep. Sur. Oldham Ld. Dist.
Tasosa, Texas
Dear Sir

Upon examining the field notes
of the vacant territory in Moore
County surveyed by you I find
errors as follows.

Survey no. 10 Blk M 1 R W. Eldridge recorded
in book B. p. 237, field note do not close Error
in Dep. 690 ws. evidently in 3rd course West
the total length of line is omitted.

Sur. #15 Blk M 1 C. E. Goben book A p. 6
field note do not close. Error in Lat 74 ws.

Sur. no. 21 Blk M. 2 A. O. Campbell
in book A, p. 12 field notes do not close. Error
in Lat. 17 ws. and the course West 38' S
should be S 89° 22' W.

Sur. no. 22 Blk M 2 A. O. Campbell
in book A p. 11 field note do not close
Error in Lat. 18 ws. and the 2nd course
West 38' S should read S 89° 22' W.

Sur. no. 23 Blk M 2 A. O. Campbell
in book A p. 14 field note do not close. Error
in Lat. 8 1/2 ws. evidently the length of 3rd
course North 1780 ws should be 1788 1/2 ws.
same as the length of 1st course, the
2 & 4th courses should read S 89° 22' W and
N 89° 22' E.

Survey no. 22 Bk M 1 B. C. Campbell
in book A page 4 contains $644\frac{3}{4}$ acres instead
of 640 acres correction or explanation required.

Survey no. 18 Bk M 1 of B. Wheatley in
book A page 96 contains $661\frac{1}{10}$ acres instead
of 640 acres, correction or explanation required.

The field notes of the following surveys
are not written according to our custom
of land surveying, for instance, you say,
thence West 38° S. and East 38° N. This should
read $S 89^{\circ} 22' W$ and $N 89^{\circ} 22' E$, again
East $4^{\circ} 32' S$ should read $S 85^{\circ} 28' E$.

Survey no. 5 Bk M 1 recorded in book A page 27	
" " 23 " " " " " "	3
" " 24 " " " " " "	16
" " 25 " " " " " "	2
" " 2 " M 2 " " B	255
" " 3 " " " " " "	256
" " 4 " " " " " "	257
" " 5 " " " " " A	22
" " 8 " " " " " "	29
" " 9 " " " " " "	30
" " 10 " " " " " "	31
" " 11 " " " " " "	32
" " 12 " " " " " "	19
" " 13 " " " " " "	18
" " 14 " " " " " "	17
" " 15 " " " " " "	15

16 Blk M2 recorded in book A page 10
 " 17 " " " " " " " 9
 " 18 " " " " " " " 8
 " 19 " " " " " " " 7
 " 24 " " " " " " " B 83

please correct your records accordingly and
 notify this office if you failed to
 return a certified sketch ^{of these surveys} showing
 connection between Block no. 44 and
 block 3 T as found on the ground.

7/26/02 