

State of Texas.

County of Presidio.

Corrections of surveys in Block one and two T. M. Ry. Co.  
September 1907.

Block 1

We found the following original corners on the ground S. E. and S. W. survey 20 also N. E. and S. E. corners survey 18 Block 12 G. H. & S. A. Ry. Co., S. E. and S. W. survey 111 and S. W. corner of survey 112 Block 7 G. H. & S. A. Ry. Co. N. W. & N. E. Cor. of survey 78 Blk. 5 G. H. & S. A. Ry. Co. In connecting all these corners together.

We found that by using a variation of 11°44' East we ran to all the above corners. With this I furnish plat showing all these above corners and Blocks field together with corrected field notes for surveys 1, 2, 3, 4, 5, 6, 7, 12, 14, 19, 21, 26, 27, 33, 39, 40 and 38.

Block 2

Begining at a rock mound at foot of a Mesquite tree 339 varas North 49°30' East from the North River corner of survey 1 Block 2 T. & P. Ry. Co. and on its North West boundry line from which a peak brs. S. 40°-3/4 W. and flat top peak brs. N. 73°-3/4 W.

Thence N. 7°-35' E. 988 varas, Thence N. 66°-05' E. 418.6 varas, Thence N. 69°-12' E. 202.6 varas, Thence N. 48°-46' E. 255.4 varas, Thence N. 35°-13' E. 568 varas, Thence N. 27°-30' E. 550 varas, Thence N. 11°-45' E. 297.4 varas, Thence N. 22°-59' E. 270 varas, 17°-13' E. 174 varas, Thence N. 1°-47' E. 217.2 varas, Thence N. 10°-02' E. 645.2 varas, Thence N. 15°-05' S. W. 215.4 varas, Thence N. 22°-24' E. 219.2 varas, Thence N. 32°-01' E. 98.2 varas, Thence N. 60°-26' E. 187.2 varas, Thence N. 10°-03' E. 478 varas, Thence N. 2°-23' E. 282.4 varas Thence N. 8°-58' W. 652.3 varas, Thence N. 12°-30' E. 799.53 varas, Thence N. 60°-12' E. 715 varas, Thence N. 21°-21' W. 705.2 varas, Thence N. 20°-40' W. 551 varas, Thence N. 2°-26' W. 230.2 varas, Thence N. 14°-53' W. 421.3 varas, Thence N. 10°-E. 274.2 varas, Thence N. 49°-12' E. 492.1 varas, Thence N. 5°-01' W. 183 varas, Thence N. 44°-29' E. 273 varas, Thence N. 32°-34' W. 220.2 varas, Thence N. 20°-29' W. 1495.3 varas, Thence N. 38°-29' E. 254.8 varas, Thence N. 24°-30' W. 321 varas, Thence N. 25°-30' W. 385 varas, Thence N. 9°-13' E. 1138.3 varas, Thence N. 8°-39' W. 660 varas and Thence S. 19°-48' W. 46.8 varas, to a pile of stones for the North River corner of survey 10 T. & P. Ry. Co. block 2 from which a cotton wood marked R bears S. 6° W. 102 varas, to a double mesquite x bears S. 24-1/2 W. 15 varas.

Thence N. 19°-48' E. 46.8 varas.  
Thence N. 16°-15' E. 493 varas, Thence N. 41°-20' E. 81.8 varas, Thence N. 57°-55' E. 1349.4 varas, Thence S. 81°-09' E. 424.5 varas, Thence N. 51°-18' E. 1681 varas, Thence N. 0°-35' E. 800 varas, Thence N. 31°-33' E. 259 varas, Thence N. 2°-58' W. 125.4 varas, Thence N. 6°-24' E. 269.6 varas, Thence N. 0°-58' W. 501.6 varas, Thence N. 18°-03' E. 223 varas, Thence N. 16°-09' E. 156.4 varas, Thence N. 2°-19' W. 540.8 varas, Thence N. 42°-43' E. 647 varas, Thence N. 8°-55' E. 417 varas, Thence N. 42°-36' E. 231 varas, Thence N. 27°-51' E. 490.8 varas, Thence N. 48°-19' E. 427 varas, Thence N. 45°-45' E. 276.6 varas, Thence N. 85°-22' E. 707 varas, Thence N. 59°-40' E. 490 varas, Thence N. 89°- E. 62.6 varas, Thence S. 45°-53' E. 490 varas, Thence S. 47°-51' E. 456 varas, Thence S. 73°-20' E. 168 varas, Thence S. 60°-35' E. 349 varas.

Thence E. 279.3 varas to W. boundry of block 12 G. H. & S. A. Ry. Co.

Thence South 506 varas to N. W. corner of survey 125 block 12 G. H. & S. A. Ry. Co.

Thence East 1900 varas passed the N. E. corner of survey 125 and N. W. corner of survey 92 block 12 G. H. & S. A. Ry. Co. at 3800 Varas to a rock mound for the N. E. corner of survey 92 from which a boulder in corner of correct brs. N. 67°-14' E. 480 varas, another boulder in the field brs. N. 75°-48' E. 351 varas.

This survey in block 2 T. M. Ry. Co. and block 2 T. & P. Ry. Co. shows as you will note from the Map quite a shortage from the original survey.

This is occasioned by a shortage of 296 varas on the West line of block 12 G. H. & S. A. Ry. Co. running from West to East and the surveys from 2 to 10 inclusive block 2 T. & P. Ry. Co. having an excess in width of 925.7 varas or an excess of 91.7 varas in each

N 31-12 E 325 W

varas

a-

Presidio County connections of Block 1 and 2 T. M. Ry. Co. continued.

survey .

The River has washed away all the corners on block 2 T. & P. Ry. Co except the ones on survey No. 1 and No. 10 block 2 T. & P. Ry. Co. that we surveyed from, to equelize the surveys on said block 2 G. H. & S. A. Ry. Co.

We allowed a width of 1041.7 varas for each survey from 2 to 10 inclusive.

We Deputy Surveyors G. F. Brooks & R. L. McCamant of Presidio County do hereby, ~~by~~ certify that the foregoing connection lines were made, actually on the ground according to law.

E. B. Baker  
C. C. Angel Campas.

G. F. Brooks  
Deputy Surveyors, Presidio County.

R. L. McCamant  
Deputy County Surveyor, Presidio County.

G. H. Brooks  
County Surveyor, Presidio County.

State of Texas.

County of Presidio.

Corrections of Surveys in Block 5. T. M. R. R. Co. made September and October 1907.

After Correcting Blocks 1. and 2. T. M. Ry. Co. with Deputy County Surveyor R. L. Mc Camant, in the month of September 1907., I made a survey from the East corner of Survey 335 in the name of John W. Spencer, to the S. W. corner of Survey 5. Block 7. H. & T. C. Ry. Co to ascertain the width of conflict of block 5. at the South end and if Survey 143 and 144 Block 1 D. & P. Ry. Co. are in conflict as shown by the Map of this county. You will find from the survey notes given below that they are not in conflict.

The bearings on the beginning and ending corners of this survey checked so that we are certain that we were at the correct corners.

Beginning at the East Corner of Survey 335 made in the name of John W. Spencer for a connecting point of this Survey.

Thence N. 46 15' E. 2481.3 vs, Thence N. 44 - 45' E. 807 vs., ~~XXX~~  
 Thence N. 27 - 29' E. 637.6 vs, Thence N. 30 - 55' E. 1977.3 vs.  
 Thence N. 25 - 03' E. 1622.6 vs. Thence N. 25 - 45' E. 1039 vs.  
 Thence N. 17 - 01' E. 1782.8 vs. Thence N. 10 - 01' E. 395 vs.  
 Thence N. 11 - 47' E. 1150 vs. Thence N. 20 - 01' E. 384 vs.  
 Thence N. 40 - 35' E. 672.3 vs. Thence N. 40 - 22' E. 495 vs.  
 Thence N. 16 - 20' E. 185 vs. to the S. W. corner of Survey 5. Blk. 7. H. & T. C. Ry. Co.

~~XXXXXXXXXXXXXXXXXXXXXXXXXXXX~~

Pablo Rodriguez. C. C.  
Silverio Salgado. C. C.

I G. F. Brooks Deputy County Surveyor of Presidio County, do hereby ~~made actually on the ground~~ according to law.

*G. F. Brooks*

Deputy County Surveyor Presidio Co

*G. F. Brooks*

County Surveyor Presidio County.

Station	Bearing	Distance	LATITUDE		DEPARTURE	
			North	South	East	West
1	N 46 1/4 E	2481	1716		1793	
2	N 44 1/2 E	807	593		568	
3	N 27 1/2 E	638	566		295	
4	N 31 E	1977	1695		1019	
5	N 25 E	1623	1471		686	
6	N 25 3/4 E	1039	936		451	
7	N 17 E	1783	1705		521	
8	N 10 E	395	389		69	
9	N 11 1/4 E	1150	1126		234	
10	N 20 E	384	361		131	
11	N 40 1/2 E	672	511		436	
12	N 40 3/4 E	495	378		320	
13	N 16 3/4 E	185	178		52	
14			11605		6575	

A-2  
V

counter 34458

Sketch File No. "K"

Presidio County

Corrections of Surveys  
By G.F. Brooks

Filed Oct. 1907 198

WM. H. McDONALD, Com'r

3/28/38 Woodland  
File Clerk

Descriptive: Corrections of  
surveys in Blocks 1, 2,  
& 5 T.M. RyCo.

For Sketches See  
Presidio County Rolled  
Sketches 42, 43, 44

5/28/38 - J.L.W.

counter 34459

213

XXXXXXXXXXXXXXXXXXXX  
XXXXXXXXXXXXXXXXXXXX  
XXXXXXXXXXXXXXXXXXXX

J. H. & T. C. Ry. Co.  
Thence N. 1/4 - S01 E. 138' 1/2' to the S. W. corner of Survey G. Bk.  
Thence N. 1/4 - S21 E. 885' 3/4' Thence N. 1/4 - S81 E. 439' 1/2'  
Thence N. 1/4 - S11 E. 1150' 1/2' Thence N. 1/4 - S01 E. 284' 1/2'  
Thence N. 1/4 - S11 E. 1988' 1/2' Thence N. 1/4 - S11 E. 892' 1/2'  
Thence N. 1/4 - S21 E. 1938' 1/2' Thence N. 1/4 - S21 E. 1033' 1/2'  
Thence N. 1/4 - S21 E. 828' 1/2' Thence N. 1/4 - S21 E. 1023' 1/2'  
Thence N. 1/4 - S11 E. 212' 1/2' Thence N. 1/4 - S11 E. 807' 1/2' XXX  
John W. Spencer for a corner of Survey 338 made in the name of

Being at the East corner of Survey 338 made in the name of  
checked so that we are certain that we were at the correct corners.  
The bearings on the beginning and ending corners of this survey  
given below are the same as on the original survey.  
shown by the Map of this county. You will find from the survey notes  
if Survey 113 and 144 Block 1 D. & B. Ry. Co. are in conflict as  
to ascertain the width of conflict of block 2. at the beginning and  
Spencer, at the S. W. corner of Survey 2. Block 2. H. & T. C. Ry. Co.  
survey from the East corner of Survey 338 in the name of John W.  
Surveyor H. J. Mc Gowan, in the month of September 1907. I will  
After Correcting Blocks 1 and 2. T. M. Ry. Co. with Deputy County  
and October 1907.

Corrections of Surveys in Block 2. T. M. Ry. Co. made September  
County of Presidio.  
State of Texas.