

Alpine, Texas  
Jan 18<sup>th</sup> 1915.

RECEIVED  
JAN 18 1915  
Referred to Map

Hon J. T. Robinson  
Commissioner,  
Austin, Texas.

Answer  
1-20-15  
clock

Dear Sir:-

A few days since Mr R. S. Dal.  
sent to your office, a sketch and report of  
his work in Presidio Co. Block 330. and others.  
While down there we were told that the East  
half of 14. T. T. Bl 330 had been sold, paid  
out and patented. Mr D. says if this be true  
he would like to know it and get J. N. of it.  
to see if it has also been moved from its orig-  
-inal position on ground, same as its alternate  
No 13.

Also please send connection given in J. N. to  
orig No 767. T. T. we have it from records. but  
it leaves out one call on ground and the first  
run south, calls S 18° E 660. while it should have  
been S 18° W. 660. and the last N 12° W 190. should  
should have been N 12° E 190.

again by a thorough examination of the

LC

counter 34535

(2)

field notes in Bl 330. by placing 329 & 330  
A B + M as shown on your map. S. 7100<sup>rd</sup>  
E. 469.00 from S.E. Cor 33 in Bl WJA 2. and  
plattling 329. 930. & 468. and continuing on S-  
with Bl 330. Then place 10 beginning at SW  
Cor 9. 18. south of 9. This will then run  
17. in conflict with NW corner No 510.  
giving 18. 640 acre and necessitate correction  
of 17. to 28 W. P. Couch. Mr Dod was of  
opinion at first that 17. fitted north of 28.  
But this is not true. part of 28. will be  
east of 17. and balance S + W of 17. the  
W-end of 28 run in on 2. A. Upton. No 6  
Bl 362. is covered partly by 14. No 4. C L Taylor  
Bl C 3. and 15 + 16. T. J. Bl 330. S. R. Thompson's  
survey of Bl C. 3. shows to have accepted a  
line of fence (now down.) that was supposed to  
have been on S-line of 34. Bl WJA 2. which  
is situated 370 var north of S-line. making  
No 2. Upton 1389. S. to reentrant corner of 14.

(3)

instead of 10190 as. from the SE corner of  
5 in Bl 23. west 10250 to west line of  
33 Bl W.S. & 2. instead of 950 as shown by Town  
figured by connection west from S.W. cor 2. Block  
N.S. & 2. to Bl 23. Bl 23. runs South at  $12^{\circ} E$ .  
while Bl W.S. & 2. runs at  $11^{\circ} 30' E$ . Then No 2 & Upton  
conflicts with 33 & 34. 12500 as at North & 15000 on  
S. end. surveys 21 & 22. J. Hardiman slightly con-  
flict with N side of 33 & 34. Bl W.S. & 2. and are on  
top of No 2. Upton. S. line 5. Bl 23 and N line  
22. very near parallel each other. 22 being a little  
to south.

Again taking Mr Dods, <sup>run</sup> west from S cor No. F.  
Bernandez, on Alawits Cr. to L. Fuentes survey in  
Bl 1. D & P. difference in Variation added to his South-  
ing amounting to 200 var. will place N-Block line of  
1. D & P. along S-line 15 & 16. Bl 330. approximate  
same as Thompson made it.

If your Draftsman will note these facts it will greatly aid  
in plating.

Yours Truly,  
D. A. Hector Surveyor

Sketch File No. 46-Box 2

Presidio Court

Presidio County  
Sketch files

Recd 1/18/15

Jan. 18th, 1915 - 193

J. H. Walker, Com

File Cl

Descriptive:

County 34538

LC3