

16.

C D Footes' SK. & FN. to locate
#63, 64, 65 & 84, T & NORY Co.
Filed Oct. 8, 1879,

center 38174

*Atlanta Co.
San Sabae Co School*



Scale 2000 ft. = 1 inch

Sketch of Part of Tazewell Co.

counter 38175

Field notes of a survey made to
find Survey 63, 64, 65, + 84 Texas + Mo.
R. R. Company.

Began at the S.W. cor of Survey 201
N. C. Ottlands,

a stone mound, from which a d. O.
7" bro N. 74 W 34100, do. 768 8000, a d. N. 28 W.

Marked ∇

Thence run East, at 168000. Crossed bank
at 198600 a stone mound, with bearing
trees - a Mus. 6" N. 84 W 7000, do 8" N 8 1/2 W 8100.

One tree had been cut down, the other
was plainly marked.

Thence N. 45 E at 271700 found stone Mch.
proper distance for which would be 268700.
Found bearing trees at proper distance from
corner, but bearings were as follows =

Sorted d. O. was N 68 1/2 E 17 Triple do. N 7 1/4 W 8000

Thence East, at 142200 crossed a branch
recrossed at 190000 - found no corner.
Plenty of Mus + d. O. timber but could
find no marked line -

at 200000 crossed creek to North side

" 2100 " crossed " South side

" 2400 " " " to North side

" 5800, Spent an hour hunting cor
described in field notes for Sur. 17.

B. M. Co. but found none,

Continuing East, at 5842 vs. the
S.E. Cor of Sec 33 T60 R11M had was 182 vs. to
the South. Field Notes call for Trip 20,
S 18 1/2 E 260 vs + a Mes. N. 2 1/2 E 110.

From a point 220 vs from the S.O. both
trees have the proper bearing, and the
Mes. has the proper distance both trees
have ancient marks.

Then ^{from the corner} continuing East, at 400 vs
crossing Crownest Cr. at 950 vs found
a stone Md. No bearings to be found.
at 1900. searched but found no corner.
at 2850 vs. a stone mound. No bearings
at 3800. a ~~stone~~ stake with bearing
trees Mes 10" N 70 3/4 E 28 1/2 vs. do. 12" N 10 1/2 W 58 vs.
(Had no notes for this corner dont know how it agrees
with survey notes)

Then continuing East, at 950 a st Md
No bearing trees.

at 1875 crossed branch
at 1900 a stone Md. Mes 10. N. 30 1/2 E 56 vs
do. 8" N 15 1/4 E 58 vs. (Had no notes for this)

This Cor shows on the map to be the N.W
Cor of Sec 62. T11N0R11E.

Then South at 1875 vs found bearing
trees, which fitted nothing I had, + at
1996 vs. found a stake + bearing trees
described for SW corner of Sec. 62 -
Mes 8" S 86 W 37. do. 10" N 07 W 58 vs. counter 38177

Continuing South from SW corner of
62 - At 1900⁰⁰ found no corner.

At 3700⁰⁰ found the SW cor of 64 7.1⁰⁰.
88⁰⁰ to Right (west) -

A. Mes. N 78 $\frac{1}{2}$ E 100⁰⁰. do 11" S 9 $\frac{1}{2}$ E 13⁰⁰.

Found an ancient & plainly marked
line 156⁰⁰ south of this corner, bearing
East -

Thence, from SW cor "64." East, at 1000⁰⁰,
crossed branch, at 2061 ⁰⁰ found
the corner, between 64 & 65. 156⁰⁰ to the
south & on the marked line before
referred to.

Found old stake, from which a Mes. 5"
brs N. 78 $\frac{1}{2}$ W 25⁰⁰. do 12" S 80 $\frac{1}{2}$ W 68. (Trus plainly
marked)

Thence East, found old marked line
all the way - at 1985⁰⁰ found old stake
& bearing trees. Mes. 4" S 80 $\frac{1}{2}$ E 7. do 10 S 84 $\frac{1}{2}$ W 22

Thence East at 1900⁰⁰ found no line
or corner.

Thence North, at 900⁰⁰ cross creek.

Went thence, to find Surveyors
937 Leon Smith, & the block of surveys
attached. -

Beginning on the North Bank of
Concho, opposite N. W corner of Sur 574

German Em Co. which lies for bearings
an Elm 18" N 81° E 3200, do. 12561 W 1800, & which
I found.

Thence North 109400.

Thence west at 1032100 found stone mark,
with bearing trees, a Mes. 5" S 64 E 3800.

do. 6 S 17° E 5800.

Trees plainly marked & exactly fitting field notes
for S. E. cor of Sur 937, in name of Lou Smith

Thence North, at ^{53 1/2} 770 1/2 00, intersected old
marked line.

At 712 1/2 intersect line run east from
S.W. cor of Sur 641 7th N. O. R. R. at a point
74800. East of the S.W. cor of 64. 7th N. O. R. R.
at 190000, the N. E. corner of Sur 937.

Found one bearing tree a Mes. 10"
N. 49 1/2 E 118 1/2 00, & marked plainly, and the
remains of a Mes. N 64 W. 86 1/2 00.

Thence west, finding no corners,
crossed Crow Nest Creek at 242200.

At 380000, searched for N. W. corner of
Sur 944. Timber all cut away & found
no marks. At 414000 cross a creek
at 2980. found corner described as
N. W. cor of Sur 943, Mess Ernest, St. Mount.

A. Mes. 8" S 85 1/2 E 15600, do. N 9 1/4 E 106

The corners described in field notes
of Bastrop Mfg Co. do not correspond

With the corners they join to, and I
could not find any others, any cor-
ners corresponding to those described
in B. Nuy Co Surveys, and

C. D. Howe

Co Surveyor

Tomlinson

File: 16.

Tom Green County

Filed Octob. 8/79.

Rhoads Fisher,
Cly. C. C. Co.

counter 38181