



campers school
 Sept 1907 ✓ 10' at date of new map Slaney & Fortner
 May 17 1907 ✓ figures at 9' to
 corresponds with lines
 ran for River Survey
 about solid part orig cor
 m.s. N 21 1/4 E 27 1/2 to
 other corner
 n.b. of " m N 3/4 E 10 1/2
 n.b. of " n 43 W 24 1/2
 trees cut down

I Geo. Myers Co Surveyor Zavala Co Tex
 hereby certify that the sketch truly
 represents survey & plat as shown
 as I found them on the
 ground in 1907
 witnesses my hand this 15 day
 of July 1915 Geo Myers
 Co Sur Zavala Co

counter 41416

1187

Batesville Tex 7/22/1915

Mr J. F. Roberson
Cann Land Office
Austin Tex

RECEIVED

AUG 2 1915

Referred to Map

Dear Sir

One of the surveyors who ran
lower line of Garala County stated to me
that he searched for N Corners but failed
to find a single corner in that Block
and taking my report as East Run of
County they estimated where they would be
May 20th 1915

I began an bore line at the original N.E. Cor 74
post with both original bearings & stump of
mesic 238E 30" the double mes N N E 20
that post containing marks has been buried
N. 6. M. 6. 6 3/4 E 16 1/2"
M. 6. 44 1/2 E 24 3/10"

Then South. S. 9. 23 an old line by myself in
1900 - 1900 a post 279 1/2" found 1/2" as
East from org 3x mile post found by me
down on South side of an old road marked
XXXIV 21. 2 as the post was post by
decayed I had a wire post around it and
set up in a way near by also post new post
on the marked line I also took the following
bearings 3 M in a cluster 55-8'-E 1/2"

4 long m 24 in at bottom N 66 W 70
Line N 81 1/4 W. I also found the mile
post 3 miles East of that point by my
lawyer and it was west of Ref. by. Line

The County line and forby line run same
Course reading County line 9. 13.

In running Eastern County Line I
represented Garala Co. Located up and connected
to Corners in same way of line as the 1st
counter 41417

24114 00. 24. 1911

County man ran and measured the line proper
so I plead not ~~guilty~~ guilty to the
~~over~~ running that is in that line
and it was the over running which he
caused surveyors to miss an ladder
line I was in General Correction
that I get the benefit of the error
I was at Corizo Springs. Cause was
Cauk in session and I notified them
in writing I would level the line up
and cause to it

At my hand this 21st day July 1911

I have since notified surveyors of that
at an unit Co of my friend

Geo. Myers
County Surveyor Javalco Co

OFFICE OF
GEO. MYERS
SURVEYOR, ZAVALA COUNTY

OFFICIAL DIRECTORY:
County Judge and
Ex-officio County Superintendent,
O. A. STUBBS
County Attorney,
JOHN C. JACKSON
Sheriff and Tax Collector,
I. E. HALL
Tax Assessor,
H. C. GOODSON
County and District Clerk,
G. C. JACKSON
County Treasurer,
W. O. DAY
County Surveyor,
GEO. MYERS

BATESVILLE, TEXAS.

7/7/15

Man J. P. Robeson
Coun. Genl. Land office

Austin Texas

Dear Sir

I am sending you corrected
note as we now have the survey
no mistakes have been made there is
a shortage between lower corner & corner
and lower corner of the corner I believe

Mr. Leland in locating a small survey
supposing there was no shortage took up
2550.00 (approximately) & in turn ran from
lower corner of the survey taking 2550.00.

Mr. A. B. Langerman applied for survey
of the entire strip and after cant est between
him and Mr. Leland with deed file
in reality 1/2 of the shortage should
have been charged to Cortez.

Yours truly
Geo. Myers

Han J. P. Robinson
Dr Sir

An account of differences
in variation and form of the long lines
I will have to send corrected notes of
5 surveys 1119, 9W 24 516 4W 1 P

1 & 2 Y C, S F, I will send
corrected sketch of those surveys Monday & Tuesday
counter 41420 Yours Truly Geo. M. M.

Wm J. G. Robinson
Cand. Genl Land Office
Austin Texas

Paterwell Texas May 5th 1915.

RECEIVED

MAR 16 1915

Dear Sir

Referring to the fact that I do not report finding original N.E. Cor. Sec. No. 11. or N.W. Cor. No 19 or any sign of either of these corners I wish to say that I spent of us speak parts of 3 days at this point trying to identify any thing that would show where either of these more or less well placed examining every thing in line 6000 N 2000 W and 4000 E of where line runs west 1/4 4th E from the original N.E. Cor No. 19 tree standing dead but marks very plain and north direction 9.45 from original N.E. Cor stump tree having been destroyed by storm but still shows the marks very plain young growth around the root intersection of said lines locate the corner.

At especially near N.E. Cor No. 11 are evidence of several trees having been destroyed by fire some evidence but not as strong near N.W. Cor No. 19.

Mr Grant Sinclair son of Dr. Sinclair died owner of the Ranch says six years ago there was a prairie fire through that section and on the particular spot quoting his language "the fire was very hot destroying many trees" burned and by the roots.

The N.W. Cor. of T. Salto determined by calculating meander and protracting from original N.W. Cor. Station to well line No 378 the N.W. Corner places the corner in a very rough travel among live oak trees.

The language of the survey is in locating the survey "take an N.E. bank of River immediately opposite the upper corner No 376 for a corner of the survey" had me to believe that the Salto corner was marked when the river turn west this would make the strip about 1460 under (N + S) but when after careful examination when at that point I failed to find evidence of the corner. These loc protract the corners of said survey

Wm J. G. Robinson

John J. P. Robinson
Cash Lead Land office
Austin Texas
Dear Sir

Referring to a discrepancy of 3000
in notes of 1102 & 1104 I feel sure they will
come together on the ground.

The discrepancy is the result of same lines
which were run to objects; my book in 1911
contains with 300 of closing the 3000 while
the other connections show it

I have wondered both persons so that they
need not cause confusion in the future
also state the fact that the closing line
of Lewis Jones shows error 480 which helps
in getting every thing straight

7/17/15

Yours truly
J. J. P. Robinson
C. L. C.

No 23 Recalculated Rechecked

	NW	S 1/4 E	N 1/4 NE	S 1/4 NW		
N 1/4 E 2013			2013		2013	
Sum S 1/4 E 1969		1968			000	
S 1/4 NW 2490				2491	2491	
S 1/4 E 788	333		713		4769	1.471.597
N 25 NW 1128	1023			473	4032	4.124.706
S 1/4 NW 449	449				4508	2.024.094
N 1/4 NE 241			241		4267	
S 1/4 NW 163	163				4046	656.235
	<u>1968</u>	<u>1968</u>	<u>1968</u>	<u>2967</u>		
N 1/4 E 1103	N 25 NW	S 1/4 E	N 1/4 NE	S 1/4 NW		
S 1/4 E 420			420		430	
S 1/4 E 1128		1128			00	219.2070
S 1/4 NW 1243				1243	1243	2.264.746
S 1/4 NW 911	911				2486	2.764.746
S 1/4 NE 822	3		822		1664	4.992
S 1/4 NW 213	213		1		848	179.133
						2.2448.871
	<u>1127</u>	<u>1127</u>	<u>1243</u>	<u>1243</u>		1244.305
N 1/4 E 1104						
S 1/4 NE 667	667		3		1063	708.021
S 1/4 NE 530			2	530	530	
S 1/4 E 911			911		000	
S 1/4 NW 46					46	19.900
S 1/4 E 564			564		92	11.100
West 1921	810		810		1741	1.225.230
S 1/4 E 1254			1254		2320	
	<u>1477</u>	<u>1477</u>	<u>1787</u>	<u>1787</u>		
N 1/4 E	N 1/4 NW	S 1/4 E	S 1/4 NE	S 1/4 NW		
West 2175	920			1974		
N 1/4 NW 668	668					
S 1/4 NW 165				165		
S 1/4 NW 792	792					
S 1/4 E 501			501			
East 2490	1053		2258			
South 1464	1327		619			
	<u>2280</u>	<u>2280</u>	<u>2757</u>	<u>2758</u>		

counter 41423

Jan 21 By Myers 4/5/1906
 267 - from file of steam raised by myself 3290
 at Rock Mt & E on no 2 4140 wire fence
 line from remaining below fence line which was
 the line 265W 2200 on of fence 90 N 25W
 from a line from from Old on River
 from from line N 25W 16950 N.E. on of low pasture
 Myers Record page 176

Myers Record page 30 Jan 4/1899

from NW on Collins to River 1105
 165E 8020 N 25W 1600 on
 165E 8020 N 25W 1600 on

	N	E	W
South 85	85		
265W 2200	2200		
N 25W 1027	1027		
165E 295	295		
	<u>1055</u>		
	1015		
	<u>40</u>		
	930		
	930		
	<u>125</u>		
	1015	268	
			1994
			444
			<u>2438</u>
			268
			<u>2170</u>

3255 1695
 3260 168
 295 1027

1813 825
 181 82
 1994 930

906 425
 18 185
 6
 930 644

181 82
 82 38
 268 127

Practically agrees with
 Mr Ross E+W

Fence line is correct
 Notice

Work by Myers 9/6/1911 Aug 12/4/1911 along wire fence
 the SW end no 11 105 is north of the line same

	N	E	W
165E 3253			
579E 1963		375	1937
575E 712		2	7
550E 582		34	47
560E 345		2	3
543E 150		11	10
548E 15		10	11
161E 66 3/10	31	124	687
879E 700	53	568	2761
N 53	84	50	556
		484	2707
		<u>477</u>	504
		07	504

3255 1695
 3253 168
 3022

165E 302
 165E 668
 8
 272
 2
 274
 182
 556

982 191
 883 172
 59 11
 3 1
 1937 375

54 25
 7 282
 605 274
 128 182
 477 556

982 191
 883 172
 59 11
 3 1
 1937 375

2200
 2170
 27

the mark was carefully done
 in a settlement
 work shows little excess
 over Mr Ross calculation

Over

By Benson and myself 17/18/1907

By Red car as a Dodge

165E 12500

— Cook 452600 with Line No 21

South 3690 for car no 21

South 3337/100 to old Rock md & E Cor No 21

2900000. 21. Feb #44

Meadow ... May 29 1856

msw 2nd 7658 16572

S 138 148		130	70	
S 102 118		106	51	
S 398 130		126	31	
S 118 42		37	21	
S 234 137		137		4
S 208 73		73		
S 414 204		178		99
S 178 33		33		5
S 144 268		208		169
N 250 54	54			
N 118 83	66		50	
S 47 277		24		74
	120	1052	223	351
		120		223
		932		128
N 478 77	24		77	
S 12 283		66		50
S 218 54		54		
S 218 151		151		
S 178 30		25	16	
S 79 140		81	113	
S 45 58		54	21	
S 85 100		50	87	
S 128 63		56	28	
S 86 30		15	26	
S 198 64		53	36	
S 78 90		54	72	
S 178 35		29	19	
S 498 1-		1		
S 20 26		689	495	50
S 100		24	50	
		665	445	

Co stump 4 x 100 100
 Fo 13 581'-w 89/10
 Hook 6 466'-w 2 3/10

Hook 7 417'-w 4 1/10
 " 9 417'-w 4 1/10

4120
 120
 3992
 4060

4120
 2850
 1270
 1532
 832
 500

above
 a E Hedge
 all ringed
 found.

cal glass out down but
 still hanging
 165 1/2 - w stump
 meg stump and
 104 x 1/2 3 1/2 -
 5.6 m 12 586 12

1851
 445
 2405

2850
 2410
 436

Box 2. 44.

Zavala Co.

Statements & sketches
by.

Geo Meyer

Filed June 2-1922.

F. Matzow
clerk

counter 41427