

Hansford Co ~~3~~ Bdry Line 1

Hansford-Sherman
County Boundary

By W.D. Twichell - 1898.

< See F/NS Filed 10-22-'28 >

I, G. J. McKay, County Judge in
and for Hansford County
State of Texas, do hereby certify
that due notice was served
in me as prescribed by law,
by the County Court of Sherman
County Texas, giving notice of
the survey of the west line
of Hansford County.

Witness my Official Signature
this 13th day of May 1898

G. J. McKay.

County Judge
Hansford County T.

Certificate of notification
filed in the Genl Land
Office July 18th 1898.

The State of Texas.

Hansford

County of Potter.

Field notes of a survey of Potter county's East boundary, the same being Carson county's West boundary.

Beginning at a monument in the drain of a ridge but not in a position where it is liable to be washed away marked on N. side 100 m. W.L. marked on E. side T.T. on S. side N.E. cor. Texas, marked on W side 36 deg. 30 min. N.L. A large stone set in ground the N.E. corner of Lipscomb county,

Thence W., at 35 vrs. a rock marked \equiv on N., \equiv on E., \equiv on W., and set in ground, at head of ravine.

At 487 vrs. cross ravine, at 712 vrs. cross ravine.

" 1352 vrs cross ravine at 1612 vrs. cross ravine

" 1900.8 " 1st., mile.

Thence W. at 39 U.S. zinc cone marked \equiv on E., \equiv on W. and 4 pits

" 592 cross ravine at 1052 vrs., cross ravine

" 16x22 vrs., cross ravine at 1900.8 vrs., 2" mile

Thence W. at 577 vrs. cross ravine, at 998 vrs. pass U.S. Mound and 2 pits at 1232 vrs. cross ravine, at 1900.8 vrs 3" Mile.

Thence West, at 51 varas U.S. zinc cone marked \equiv on E. side, \equiv on N. side, and \equiv on W. side bears N. 9 12/100 vrs. $\frac{3c}{R28E}$

at 320 cross ravine, at 760 cross ravine, at 860 cross ravine, at 1440 vrs. cross ravine, at 1900 8/10 vrs. 4" Mile.

Thence W., at 57.3 vrs m⁷, and 3 pits N. 11.7 vrs

at 420 vrs. cross ravine at 630 vrs. cross ravine

at 1280 vrs. " " at 1880 vrs. " "

at 1900.8 vrs. 5" mile.

Thence W. at 135 vrs. cross ravine at 1280 vrs. U.S. mound and 3 pits brs., N. 24 vrs. at 1640 vrs. cross ravine at 1764 vrs.

cross ravine at 1880 vrs. cross ravine at 1900.8 vrs. 6" mile

Thence W. at 1283 vrs U.S. zinc and 3 pits corner brs. N. 20.7 vrs.

at 1255 vrs. cross ravine at 1900.8 vrs. 7" mile, whence

Mrs. Cox' house brs. about N.E., 600 vrs. Observe meridian and correct.

Thence W. at 1497 vrs. cross long deep ravine, at 1900.8 vrs 8" mile.

Thence W. at ~~208~~ 208 vrs. cross ravine at 530 vrs. cross ravine

at 775 vr. cross ravine at 1252 vrs. U.S. zinc corner

brs. N. 24.3 vrs. at 1640 vrs. cross ravine at 1737 1/2 vrs

3 wire fence corner brs. S. 40 vrs. at 1900.8 vrs. 9" mile.

Thence W. at 266 vrs. cross ravine at 450 cross ravine

at 810 vrs. " " at 1900.8 vrs. 10" mile.

Thence W. at 240 vrs. " " at 995 vrs. cross ravine

at 1200 vrs. cross creek at 1258 vrs. U.S. zinc corner

brs. N. 31.3 vrs. at 1900.8 vrs. 11" mile.

Thence W. at 115 vrs. cross ravine at 585 vrs. cross ravine

at 1470 vrs. " " at 1685 vrs. " "

at 1900.8 vrs. 12" mile.

Thence W. at 282.8 vrs. cross 2 wire fence. at 520 vrs. cross ravine

at 590 vrs. cross ravine at 1262.2 vrs. U.S. zinc

~~corner brs. 84.8xxxxxxvrs~~ ~~at 1750 vrs. cross~~

~~corner at 1900.8 vrs. 13" mile.~~

Hansford Co. Entry Line 1

Hansford Co. Entry Line 1

- corner hrs. 37.1 vrs N. at ~~REINXVWYXZKXKXKXKXKX~~ 1404 vrs. cross cañon
at 1730 vrs. cross cañon at 1900.8 vrs. 13rd mile.
- Thence W. at 160 vrs. cross cañon 80 vrs. wide, at 320 vrs. leave
bluff at 430 vr. point of bluff at 941 vrs. cross 3 wire
fence at 1519 vrs. cross Kiawa river at 1900.8 vrs. 14th mi.
- Thence W. at 1282 vrs. U.S. zinc corner hrs. N. 45.5 vrs.
at 1900.8 vrs. 15th mile. (Clark's monument not to be found,
probably destroyed by buffalo)
- Thence W. at 20 vrs. cross ravine at 1145 vrs. cross ravine
at 1528 vrs. " " at 1870 vrs. " "
at 1900.8 vrs. 16th mile
- Thence W. at 480 vrs. cross ravine at 740 vrs. cross main ravine
at 1290 vrs. U.S. zinc and 3 pits corner hrs. N. 51.6 vrs.
at 1600 vrs. cross ravine at 1900.8 vrs. 17th mile.
- Thence W. at 355 vrs. cross ravine at 16 vrs. cross ~~xx~~ wire fence.
at 620 vrs. cross ravine at 680 vrs. cross ravine
at 1460 vrs. " " at 1820 vrs. cross 3 wire fence
at 1900.8 vrs. 18th mile.
- Thence W. at 68 vrs. cross ravine at 335 vrs. cross ravine
at 710 vrs. " " at 780 vrs. " "
at 1152 vrs. " " at 4200 vrs. cross 3 wire fence
at 1292 vrs. U.S. zinc corner hrs. N. 60.7 vrs.
at 1626 vrs. cross Kiawa, N. fork at 1900.8 vrs. 19th mile.
- Thence W. at 22 vrs. recross Kiawa " " at 89 vrs. cross 3 wire
fence. at 335 vrs. cross Kiawa N. fork at 345 vrs. cross
3 wire fence at 800 vrs. recross Kiawa N. fork at 835.5
vrs. cross 3 wire fence at 1295.4 vrs. cross 3 wire fence
at 1615 vrs. cross forks of ravine. at 1900.8 vrs. 20th mile.
Observe meridian and correct
- Thence W. at 290 vrs. cross ravine at 702 vrs. cross 3 wire fence
at 1291 vrs. U.S. zinc corner hrs. N. 67 vrs. at 1900.8 vrs
21st mile
- Thence W. at 560 vrs. cross head of cañon at 1445 vrs. cross deep
ravine. at 1900.8 vrs. 22nd mile
- Thence W. at 25 vrs. cross deep ravine at 474 vrs. cross 2 wire fence
at 785 vrs. cross cañon at 1235 vrs. cross cañon
at 1290 U.S. zinc corner hrs. N. 75 vrs. at 1815 vrs.
cross cañon at 1900.8 vrs. 23rd mile
- Thence W. at 440 vrs. cross head of cañon at 710 vrs. cross head of
cañon at 1654 vrs. cross forks of cañon at 1900.8 vrs.
24th mile 10 vrs. from E. side of Dodge City and K trail
- Thence W. at 640 vrs. enter valley of North Fork at 320 vrs. cross
ravine at 1100 vrs. cross S. prong of N. fork of Kiawa
at 1297 vrs. U.S. zinc and 3 pits corner hrs. N. 81.2 vrs.
at 1900.8 vrs. 25th mile.
- Thence W. at 328 vrs. cross ravine at 460 vrs. cross ravine
at 1280 vrs. cross ravine at 1900.8 vrs. 26th mile.
- Thence W. at 240 vrs. " " at 500 vrs. cross ravine
at 1160 vrs. " " at 1504.4 vrs. U.S. zinc corner
hrs. N. 82 vrs. at 1570 vrs. cross ravine at 1900.8 vrs.
27th mile. Observe meridian Polaris in eastern elongation
error 2' L. Magnetic declination at 7-22 A.M. on June 23rd
1897 = 10 deg. 55 min. E.
- Thence W. at 825 vrs. cross ravine at 1215 vrs. cross ravine
at 1900.8 vrs. 28th mile

- Thence W. at 480 vrs. cross ravine at 605 vrs. cross ravine ^{R23E}
 at 1304 vrs. U.S. zinc marked ^{R24E} S31 on E., ^{Sc} TIN on N., and S36 on W.
 and 3 pits hrs. N. 82 vrs. at 1435 vrs. cross ravine
 at 1540 vrs. cross ravine at 1900.8 vrs. 29th mile.
- Thence W. at 1900.8 vrs. set large stone marked N.E. OCHILTREE,
 N.W. LIPSCOMB, in ground and dig 4 large pits. Long's mound
 and 4 pits N.W. corner of 1029 B.L. 43 H & T.C. hrs. S. 7
 miles and 960 vrs. and E. 1 mile and 1848 vrs.
- Beginning at stone set in ground for N.E. corner of Ochiltree,
 Thence West at 1300 varas U.S. zinc and 3 pits corner bears N. 89.7
 varas at 1900.8 vrs. stone marked 1-29 set in ground and
 4 large pits for 1st mile west on Ochiltree North line.
- Thence West at 1900.8 set stone marked 2,28 and dig 4 large pits for
 2nd mi. W.
- Thence West at 50 vrs. N.E. Edge of "lake basin", at 1900.8 a stone
 marked 3,27 and 4 large pits for 3rd mile.
- Thence West, at 460 vrs. cross wagon road, at 545 vrs. cross ravine,
 at 1900.8 vrs. a stone marked 4,26 and 4 large pits for 4th
 mile. ^{R22E} S31 ^{Sc} TIN ^{R22E} S31
- Thence West, at 1304 1/2 vrs. U.S. zinc marked S31 on W., TIN on N., and S31
 on E., and 3 pits corner bears North 84^o; at 1700 vrs.
 cross ravine; at 1900.8 vrs. a stone marked 5,25 and 4 large
 pits for 5th mile.
- Thence West at 1900.8 vrs. a stone marked 6,24 and 4 large pits for
 6th mile.
- Thence West at 1000 vrs. enter and at 1220 varas leave "lake basin",
 at 1312 vrs. U.S. zinc and 3 pits corner bears North 84
 varas; at 1900.8 a stone marked 7,23 and 4 large pits for
 7th mile.
- Thence West at 1560 vrs. cross small basin, at 1900.8 a stone marked
 8 and 22 and 4 large pits for 8th mile,
- Thence West at 1318 vrs. U.S. zinc and 3 pits corner bears North
 79.6 varas. at 1900.8 varas a stone marked 9,21 and 4 large
 pits for 9th mile
- Thence West at 1100 cross ravine (error in preliminary 10 minutes
 caused by wind. Correct by meridian observation)
 at 1900.8 vrs. stone marked 10,20 and 4 large pits for 10th mi.
- Thence West at 1355 U.S. zinc marked ^{R21E} S36 on W., ^{Sc} TIN on N., and ^{R22E} S31
 and 3 pits corner bears N. 71.4 vrs. at 1900.8 vrs. a stone
 marked 11,19 and 4 large pits for 11th mile.
- Thence West at 160 vrs. across ravine. At 1900.8 vrs. a stone marked
 12,18 and 4 large pits for 12th mile.
- Thence West at 290 vrs. to 410 vrs. across lake basin at 770 to
 1055 vrs. across lake basin. At 1329 vrs. U.S. zinc corner
 bears North 68.8 vrs. at 1900.8 vrs. stone marked 13,17 and
 4 pits for 13th mile
- Thence West at 1900.8 vrs. stone marked 14,16 and 4 large pits for
 14th mile. whence Long's monument 50 ft. in diameter and 3
 ft. high bears West 406 vrs. and South 894 vrs. said monu-
 ment being N.W. corner sur. 44, H and T.C. cert. 5277
- Thence West at 1325 vrs. cross Ochiltree and Liberal road at 1341 vrs
 U.S. zinc corner bears North 62 1/2 vrs. at 1900.8 vrs. a
 stone marked 15,15 and four large pits for 15th mile.
- Thence West at 1900.8 vrs. a stone marked 16,14 and 4 large pits
 for 16th mile.

N²
 v. canal # 34237 mtd. - 00 broderick

- Thence West at 1347 vrs. U.S. zinc and 3 pits corner bears North 60.3 vrs. at 1900.8 vrs. stone marked 17,13 and 4 pits large pits for 17th mile. Thence W. at 220 cross ravine, at 1900.8 stone marked 18,12 and 4 pits for 18th mile
- Thence West at 900 vrs. cross wagon road at 1348 vrs. U.S. zinc and 3 pits corner bears north 56.9 vrs. at 1570 vrs. cross ravine head of Fulton Creek. at 1800 cross ravine, at 1900.8 vrs. stone marked 19,11 and 4 large pits.
- Thence West at 720 vrs. cross ravine, at 970 vrs. cross wagon road, at 1650 vrs. cross ravine, at 1760 vrs. cross ravine head of Sand Creek, at 1900.8 vrs. a stone marked 20,10 and 4 large pits for 20th mile.
- Thence West at 1353 vrs. U.S. zinc and 3 pits corner bears North 56.7 vrs. At 1900.8 vrs. stone marked 21,9 and 4 pits for 21st mile.
- Thence West at 1345 vrs. Dodge City and Tascosa trail, at 1900.8 vrs. a stone marked 22,8 and 4 large pits for 22nd mile.
- Thence West at 70 vrs. cross Ochiltree and Liberal Road, at 460 vrs. cross ravine, at 730 vrs. cross ravine, at 794 vrs. long circular trench 50 ft. in diameter bears S. 1624 vrs. at 1351.1 vrs. U.S. zinc and 3 pits corner bears North 47.5 vrs. at 1900.8 a stone marked 23,7 and four large pits for the 23rd mile
- Thence West at 1580 vrs. cross Creek, at 1900.8 vrs. a stone marked 24,6 and 4 large pits for 24th mile. meridian observation error / R. Magnetic declination June 27 at 6-30 A.M. 11 deg. 4 min. E.
- Thence West at 410 vrs. cross ravine, at 1880 vrs. cross ravine, at 1900.8 vrs. stone marked 25,5 and 4 large pits for 25th mile
- Thence West 1340 vrs. cross ravine, at 1900.8 vrs. stone marked 26,4 and 4 large pits for 26th mile.
- Thence West at 440 vrs. cross ravine, at 1358 vrs. U.S. zinc corner bears north 45.9 vrs., at 1500 vrs. cross point of bluff at 1774.6 vrs. cross 2 wire fence, at 1900.8 vrs. stone marked 27,3 and 4 large pits for the 27th mile.
- Thence West at 265 vrs. cross ravine, at 500 vrs. cross wagon road, at 1080 vrs. cross ravine, at 1900.8 vrs. stone marked 28,2 and 4 large pits for 28th mile.
- Thence West at 575 vrs. cross wagon road, at 700 vrs. cross ravine at 995 vrs. cross ravine, at 1295 vrs. recross road, at 1352.2 vrs. U.S. zinc corner bears north 50.9 vrs. zinc marked ^{R18E} _{S36} on West, ^{Sc} _{TIN} on North, ^{R19E} _{S31} on East; at 1900.8 vrs. stone marked 29,1 and 4 large pits for the 29th mile.
- Thence West 937.1 vrs. cross 3 wire fence (Aubrey's) at 1567 vrs. cross Aubrey's W. fence, at 1660 vrs. cross Palo-Duro Creek at 1822 vrs. cross wagon road, at 1900.8 vrs. large stone marked N.W. Ochiltree and N.E. Mansford. meridian observation error 3' S. Clark's Monument # 10 bears West 363.7 vrs. N.E. corner survey # 1 Block 45 N. and T.C. bears South, 1219.3 vrs. and E. 982 vrs.
- Beginning at stone and 4 large pits set for N.W. corner Ochiltree County.
- Thence West at 363.7 vrs. pass Clark's monument # 10 (Preliminary line from N.E. corner Lipscomb County east 3.5 vrs. N.

N³ counter 572380. 09 brotznah

of this monument and stones on Ochiltree North line were set on a true line between Clark's Monuments # 10 and 15) At 1350 vrs. U.S. zinc and 3 pits corner bears north 59.4 vrs., at 1900.8 vrs. 1st. mile on Hansford North line.

2 Thence West at 170 vrs. cross ravine, at 460 vrs. cross head of ravine, at 780.9 cross Hurgate's 2 wire fence, at 1121 vrs. cross Sandy Creek, at 1900.8 vrs. 2nd. mile, whence Mt. Helen bears W. 16 deg. 41 min.

3 Thence West at 460 vrs. cross head of draw, at 895 vrs. cross head of draw, at 1294.2 vrs. 2 wire fence, at 1900.8 vrs. 3rd. mile

4 Thence West at 155 vrs. cross canyon, at 1042.2 cross 2 wire fence, at 1900.8 vrs. 4th. mile, observed meridian error 3 north. Correct.

5 Thence West at 936 vrs. cross wagon road, at 1075 vrs. W. point of hill, at 1337 vrs. cross ravine, at 1350 vrs. U.S. zinc corner bears N. 76.7 vrs. at 1900.8 vrs. 5th. mile.

6 Thence West at 780 vrs. cross ravine, at 1100 vrs. W edge of hill at 1280 vrs. edge of hill, at 1300 vrs. N. point of hill, at 1700 vrs. E. edge of hill, at 1800 vrs. top of hill, at 1850 vrs. cross ravine, at 1900.8 vrs. 6th. mile.

7 Thence West at 105 vrs. cross ravine, at 300 vrs. cross ravine, at 415 vrs. cross ravine, at 730 vrs. cross ravine, at 1233.9 cross 2 wire fence, at 1345 U.S. zinc corner bears N. 85.9, at 1505 vrs. cross ravine, at 1900.8 vrs. 7th. mile. Whence Mann's house bears in N.E. direction about 1/2 mile

8 Thence West at 80 vrs. cross ravine, at 416 vrs. cross road, at 1180 vrs. cross ravine, at 1355 vrs. cross ravine, at 1575 vrs. cross ravine, at 1900.8 vrs. 8th. mile.

9 Thence West at 1000 vrs. cross head of ravine, at 1160 vrs. top of hill, at 1345 vrs. U.S. zinc corner bears N. about 96.6 vrs. at 1560 vrs. cross ravine, at 1900.8 vrs. 9th. mile.

10 Thence West at 290 vrs. cross cañon, at 630 vrs. cross ravine, at 1188 vrs. cross ravine, at 1835 vrs. cross ravine, at 1900.8 vrs. tenth mile.

11 Thence West 500 vrs. cross ravine, at 605.3 cross 2 wire fence, at 1345 vrs. cross wagon road, at 1355 vrs. U.S. zinc corner bears N. 104.3 vrs., at 1900.8 vrs. 11th. mile.

12 Thence West at 1857.2 vrs. cross 3 wire fence, at 1900.8 vrs. 12th. mile.

13 Thence West at 1345 U.S. zinc brs. N. 115.2 at 1900.8 vrs. 13th mile.

14 Thence West at 251.8 vrs. Mr. Hitch's 3 wire fence, at 532 vrs. cross wagon road, at 1320 vrs. stone wall bears North 8 vrs., at 1697.9 vrs. cross Mr. Jno. Milligan's 2 wire fence, at 1900.8 vrs. 14th. mile.

15 Thence West 1345 vrs. U.S. zinc corner bears N. 127.7 vrs. at 1900.8 vrs. 15th. mile.

16 Thence West at 166.4 cross 2 wire fence, at 1406.2 cross 2 wire fence, at 1900.8 vrs. 16th. mile.

17 Thence West at 1168 cross wagon road, at 1345 vrs. U.S. zinc corner bears north about 140.2 vrs., 1900.8 vrs. 17th. mile.

18 Thence West at 780 vrs. Bluff, at 915 vrs. pass mound and 4 pits, at 968 vrs. cross wire fence, at 1739 vrs. cross 2 wire fence, at 1900.8 vrs 18th. mile. Observed meridian error in line 1' S.

19 Thence West at 675 vrs. cross 3 wire fence, at 734 vrs. cross Cold-water Creek, at 860 vrs. cross wagon road, at 1115.6 vrs.

74

Clark's monument # 9. (This monument was 23.8 vrs. S. of true West line from Clark's monument # 10) at 1348 vrs. U.S. zinc corner bears north about 147 vrs., at 1780 vrs. cross cañon, at 1900.8 vrs. 19th. mile on E. side Bluff.

- 20 Thence West at 560 vrs. cross cañon, at 765 vrs. cross head of cañon, at 1900.8 vrs. 20th. mile.
- 21 Thence West at 785 vrs. cross ravine, at 1345 vrs. U.S. zinc marked S32 on W. ^{SC}TIN on N. and S33 on E. and 3 pits corner bears N. 153 vrs., at 1550 vrs. cross ravine, at 1900.8 vrs. 21st. mile.
- 22 Thence West at 1900.8 vrs. 22nd. mile. ^{R14E}S36 on West, ^{SC}TIN on North and ^{R15E}S31 on E. and 3 pits corner bears N. 159.2 vrs. at 1890 vrs. cross wagon road, at 1900.8 23rd. mile.
- 23 Thence West at 705 vrs. cross wagon road, at 970 vrs. cross dim wagon road, at 1645 vrs. cross dim wagon road, at 1900.8 vrs. 24th. mile.
- 24 Thence West at 1360 vrs. U.S. zinc corner bears north 172 vrs. at 1900.8 vrs. 25th. mile on E. slope San Francisco Creek.
- 25 Thence West at 1255 vrs. cross ravine, at 1860 vrs. cross San Francisco Creek, at 1900.8 vrs. 26th. mile.
- 26 Thence West at 1175 vrs. cross ravine, at 1360 vrs. U.S. zinc corner bears North 184 vrs. at 1500 vrs. cross road, at 1900.8 vrs. 27th. mile.
- 27 Thence West at 1400 vrs. cross ravine, at 1900.8 vrs. 28th. mile.
- 28 Thence West at 1360 vrs. U.S. zinc marked ^{S36}R13 on West, ^{SC}TIN on North, and ^{S31}R14E on East, and 3 pits corner bears north 195.5 vrs., at 1900.8 vrs. 29th. mile.
- 29 Thence West at 280 vrs. cross ravine, at 1900.8 vrs. 30th. mile. The N.E. corner Sherman County. Set stone 30 by 42 inches marked N.E. SHERMAN on W. side, and N.W. HANS. on E. side and dig 4 large pits for N.E. corner Sherman County. Magnetic variation at 10 A.M. July 10, 1897 = 11 deg. 49 min. E. Observed meridian, no error in line.
- 30 Beginning at the stone monument set for the N.E. corner of Sherman County.
- Thence South at 1900.8 vrs. set stone in ground and build earth mound 2 feet high and dig 4 large pits for 1" mile on Sherman E. line.
- Thence South at 1900.8 vrs. stone and earth monument 2 feet high and 4 large pits for 2" mile.
- Thence South at 65 varas cross ravine, at 740 vrs. cross San Francisco Creek, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 3" mile.
- Thence South at 400 vrs. pass head of ravine, at 1900.8 vrs. stone and earth mound 2 feet high and 4 pits for 4" mile.
- Thence South, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 5" mile.
- Thence South, at 760 vrs. cross ravine, at 1708 vrs. cross wagon road, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 6" mile.
- Thence South, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 7" mile.

- Thence South at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 8" mile, gallon jug buried in mound.
- Thence South at 1900.8 vrs. stone and earth mound 2 feet high and four large pits for 9" mile.
- Thence South at 385 vrs. cross camp arroya, at 680 vrs. cross ravine, at 1178 vrs. recross ravine, at 1730 vrs. head of ravine, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 10" mile.
- Thence South at 1900.8 vrs. stone and earth mound 2 feet high, near head of ravine for 11" mile.
- Thence South at 1745 cross ravine, at 1900.8 vrs. stone and earth mound and 4 large pits for 12" mile.
- Thence South, at 820 vrs. cross ravine, at 1108 vrs. cross 2 wire fence at 1620 vrs. cross old road, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 13" mile.
- Thence South at 1200 vrs. observe meridian, no error in line, Magnetic Variation at 7-20 A.M. July 15" 1897 = 11deg. 39 min. E. at 1775 vrs. cross Coldwater Creek, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 14" mile.
- Thence South, at 390 varas cross wagon road, at 930 vrs. cross head of ravine, at 1700 vrs. head of ravine, at 1800 vrs. head of ravine, at 1900.8 vrs. stone and earth mound 2 feet high for 15" mile, whence round knoll brs. N. 44 deg. E., end of bluff brs. N. 45 deg. 31 min. E. North end of hill brs. S. 86 deg. 51 min. E. and S. end of hill brs. S. 79. deg. 19 min. E.
- Thence South, at 160 vrs. cross ravine, at 450 vrs. cross ravine, at 1020 vrs. cross ravine, at 1050 vrs. cross ravine, at 1900.8 vrs. stone and earth mound and 4 large pits mound 2 feet high for 16" mile.
- Thence South at 130 vrs. cross Loafer draw, at 840 vrs. top of hill, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 17" mile.
- Thence South, at 730 vrs. cross 3 wire fence, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 18" mile.
- Thence South, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 19" mile.
- Thence South, at 1660 cross old dirt road, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 20" mile.
- Thence South, at 495 and 635 cross wagon roads, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 21" mile.
- Thence South, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 22" mile.
- Thence South, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 23" mile.
- Thence South, at 221 vrs. cross ravine, at 1320 vrs. center of small "lake basin", at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 24" mile.
- Thence South, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 25" mile.
- Thence South at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 26" mile.

Thence South, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 27th mile.

Thence South at 770 vrs. cross ravine, at 1670 edge of top of hill, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 28th mile.

Thence South, at 335 vrs. cross wagon road, at 600 vrs. meridian observation, error 1' E. Correct- at 625 vrs. cross North Palo-duro Creek, at 670 and 760 recross Palo-duro, at 1900.8 vrs. stone and earth mound 2 feet high and 4 large pits for 29th mile.

Thence South at 2010.4 vrs. Large Stone Marked S.E. Sherman, N.E. Moore, Hutch, and Hans, and 4 large pits for 30th mile, whence S.E. Sherman Co. brs. S. ~~470~~ vrs. 747000

Howard Trigg }
Harry Whitcomb } Chain carriers.

I, J. M. Twitchell Special Surveyor for Randall, Potter, Moore and Ochiltree County, do hereby certify that the foregoing field notes are true and correct, and that the marks natural and artificial are truly described in the foregoing field notes and that said survey was actually made upon the ground, witness my hand this 24th day of June 1898

J. M. Twitchell, Special Surveyor for
Randall, Potter, Moore, Sherman & Ochiltree
Counties Texas

Approved this 5th day
of July 1898
J. W. Wiley
County Judge
Hansford County, Tex.

Original Survey? not on file
1901 4/10/01
E. S. V. 2nd

A. D. Aldridge & Co., Stationers, Printers and Book Binders, Dallas, Texas.

No. 318-CERTIFICATE OF RECORD.

The State of Texas, }
County of Hansford.

I, Wallace W. Kay County Clerk,

in and for said County, do hereby certify that the foregoing field notes dated the 24 day of June 1898, with its certificate of authentication, was filed for record in my office, the 5th day of July 1898, at 8 o'clock A.M., and duly recorded the 5th day of July 1898, at 12 o'clock P.M., in the records of said County, in Vol. one on Pages 1 to 16

WITNESS my hand and the seal of the County Court of said County, at office in Hansford, Texas, the day and year last above written.

Wallace W. Kay
Clerk County Court Hansford County.

By _____ Deputy.

77

Counter 54242

