

Daniel Murphy
Survey # 625

S 78° E 672 Varas.
S 78° E 768 Varas.

File # 3150.
McLain
11/4/86

S 12° W 855 Varas.
S 12° W 855 Varas.

S 39° 5' W 890 Varas.
S 40° W 890 Varas.

Survey # 257.
B.B.B. & Co.
R.R. Co.

S 50° 55' E 1120 Varas.
S 50° E 1120 Varas.

Plat of 484 Acres.
Texas to D. Murphy
Feb. 15, 1887. # 5/1652.
Certificate

Note
Inside figures are from Patent.
Outside figures are from Records of
Dist. Surveyors, Office in
Reeves Co. Texas.

Survey # 53 Blk 13. Hr & Co. N.

90°
Iron Pipe
38-53 Blk 13.

S 40° W 946 Varas.
S 39° 5' W 1349 Varas.

Survey # 258.
B.B.B. & Co.
R.R. Co.

S 50° 55' E 1000 Varas.
S 50° 55' E 1000 Varas.
July 30, 1895
A.W. Handolph
File # 7809.

Plat of 160 acres.

Texas to W.D. Johnson
assignee of A.S. Hyles.
Dated Oct. 11, 1895

Certificate # 8/1665.
Note.
Figures inside represent
Patent Notes.
Figures outside are taken
from Dist. Surveyors notes
as found in office of Dist.
Surveyor in Reeves Co. Texas.

N 78° W 911 Varas.

177
158

S 78° E 779 Varas.

206 Varas.

Survey # 52 Blk 13. Hr & Co. N.

280 Varas
6302

N 12° E 845 Varas.

3989.60

Iron
Pipe
37-38-52
Blk 13.

Survey # 259.
B.B.B. & Co.
R.R. Co.
S 39° 5' W 1434 Varas.

Corrected Line Survey # 37. Hr & Co. N.
Blk 13.

N 78° W 1071 Varas.
N 78° W 1071 Varas.