

577

Matador Tex. Feby 18, 1903.
Hon. Geo. J. Terrell Cour. S. L. Co.
Austin Tex.

Dear Sir,

Your favor of
Feby. 4, 1903 - received on my
return from a 5 weeks trip in
in lower part of Motley + N.W.
part Dickens Counties -

In reply I say that
I have corrected the errors in the con-
necting line in Dickens Co. & have
the Co. Surveyor to make corrections
on his record book, and herewith
return - together with your letter so that
you can readily take it up again -

I have done considerable
work in S.W. part of Motley
& N.W. part of Dickens - and
^{will} send in my report as soon
as I can work it up -
in. Having very severe
weather here - 10 below zero.

Will you please send me the
original map used & made by
Gasper Hays - of his work in
Dickens - I left it with
Mr. Von Rosenberg to make a
copy to file with my report.
He will remember it.

Very Truly - R.M. Kennedy

GENERAL LAND OFFICE

STATE OF TEXAS

JOHN J. TERRELL, COMMISSIONER
J. T. ROBISON, CHIEF CLERK

Austin,

2/4/03.

Mr. R. M. Kenney,
State Surveyor,
Matador, Texas.


Dear Sir:-

I return herewith for correction or explanation field notes of boundary line run by you in Dickens County. By comparing same with the sketch filed by you Nov. 3rd, 1902, you give the distance in sketch from the S. W. corner Sur. 207 Cert. 525, A. B. & M. South 1071 varas and west 2546 varas to the N. E. corner of survey 3, Cert. 334 A. B. & M.; thence west 3727 varas and north 3297 vrs to the S. E. corner of survey No. 4 Cert. 0/25 in the west line of survey 3, same certificate.

The enclosed correction reads " Begins at the original N. E. cor. of No. 3 Cert. 334 A. B. & M. and thence west 3227 varas an iron pipe the S. W. corner of No. 7 Cert. 0/26," in your sketch you have it 3727 varas. Thence with west line of No. 7 and 3 North 3297 varas an iron pipe the S. W. corner of No. 4 Cert. 0/25; this evidently should be the S. E. corner of No. 4.

Please check the correction with your work and return.

Respectfully,


Commissioner.

E. Von. R. -Wilson.

Dickens Co. SK File N

H. Von H. - Wilson

Commissioner

Respectfully,

[Handwritten signature]

Please check the correction...

and from the S. W. corner of No. 4 Cert. 0/32; this evidently
is 2254 vars. Thence with west line of No. 7 and 8 North 2204 vars
to the S. W. corner of No. 7 Cert. 0/32. In your sketch you have
of No. 8 Cert. 214 A. E. & N. and thence west 2224 vars to iron
& same certificate.

The enclosed correction reads: begins at the original N.E. cor.
E. E. corner of survey No. 4 Cert. 0/32 in the west line of sur. ev
212 A. S. & M.; thence west 2204 vars and north 2204 vars to the
1011 vars and west 2216 vars to the E. E. corner of survey 3 Cert.
in sketch from the S. W. corner sur. 204 Cert. 222 A. E. & N. South
with the sketch filed by you Nov. 21st 1908. You give the distance
of roughly the same as you in Dickens County. My connecting same

Dear Sir:

I return herewith for correction or explanation field notes

Wetmore, Texas.

H. V. H. - Wilson

[Handwritten initials]

8/4/08

GENERAL LAND OFFICE

STATE OF TEXAS