

1868.

Marlin April 27th 1868

Com of Gen Land Office

I give you here a statement
in regard to the John S Henderson
Survey A Survey being called for
I began at the SW corner of the
PB Lockridge Survey which I
identified by the bearing trees as
described in the patent of said
Survey Thence From N 30 E at
C 3276 (the distance called for in
the field notes) no marks of any
line found at 3461 varas struck the
North line of the H Cottine Survey
Thence S 65 W at 140 vars crossed a small
creek and following the marker line
continued to a point in prairie 3033 varas
for the SW corner Thence N 30 W 1000 vars
to the corner as described in patent could
not be found - made a corner as follows
a stake in lot of timber from which
a Recon bears N 4 E 10 vars marked K and
an ash bin in diameter bears N 40 E 12 vars
Thence N 62 E 5 30 vars instead of 66 2 vars
to the corner as described by an Elm
marked S 63 W 65 vars and a mesquite
stump bears S 24 E 8 5 vars

counter 22430

Thence N 38° W at 678 vrs passed a
corner made by me for the Alex
McKown S E corner at 2022 intersected
the south line of St James Survey
88 vrs S 67 1/2 W from the S E corner
of said Survey

P R J. Alexander Surveyor
of Halls County do hereby certify
that the above statement is
correct as per actual survey upon
the ground

R. de Alexander

and to whom the Surveyor of
Tazewell County
and I will meet at

~~10~~ #25

Surveyor's Statement

in regard to John S.
Hendershot's survey
R F Alexander's statement
in re, to the John S. Hender-
shot Sur.
April 27, 1868 -

Falls Co