

Field notes of connecting lines surveyed between
April 8th 1894 and May 10th 1894 in Jackson
County on the East side of Navidad River.
Variation $9^{\circ} 15' E$.

Beginning at the South or lower corner of the Eli Mercer
League a stake on east bank of Navidad River fr. wh. a
Mulberry 16" now dead and down, bears N. $10^{\circ} E$. 4 vs.
and an Ash also dead and down, the roots of which
bear S. $80^{\circ} E$. 3 vs. Thence N. $45^{\circ} E$. with a newly marked
line at 700 vs. a Live Oak 6 feet in dia. ~~4 vs.~~ to left, 1020 0, at
1321 vs. x slough, at 1424 0, at 1779 0, at 2138 0, at 2160 a
P.O. 30" nkt. = for and aft, at 2546 $\frac{1}{2}$ 0, at 2710 0, at
3382 $\frac{1}{2}$ 0 at 3600 0, at 3970 0, at 4687 0 x branch
at 4788 a P.O. 20" nkt. = on W. side 31 $\frac{1}{2}$ vs. to right.
at 4846 $\frac{1}{2}$ 0, at 5253 stake 28 vs. to right, at 5280 0
at 5788 0, at 6004.5 0 in edge of timber, at 6660 x road,
at 6666 0, at 7246 0, at 7275 x road at 7740 set stake
from which an old post bears S. $82^{\circ} E$. 84 vs. Thence N. $45^{\circ} W$.
at 610 0, at 1274.8 0, at 1741 $\frac{1}{2}$ 0 at 1832 x fence, at 2095 $\frac{8}{10}$ 0,
at 2746 x road, at 2839 0 at 3300 x branch, at 3480 $\frac{8}{10}$ 0
at 3550 old stake for corner;

Beginning at a stake on E. bank of Navidad River
from which a Peach 12" now dead N. $18^{\circ} W$. 1, a do. 9" N. $65^{\circ} E$.
3 vs. the upper corner of the Eli Mercer League; thence
N. $45^{\circ} E$. at 397.3 0 at 608 x road, at 656.2 0, at 1010 $\frac{1}{2}$ 0
at 1342 0, at 2105 $\frac{1}{2}$ 0, at 2400 0, at 2743.8 0, at 3189 0
at 3664 0, at 3952 $\frac{1}{2}$ 0, at 4240 0, at 4459 0, at 5018 0,
at 5280 leave timber at 5480 $\frac{1}{2}$ 0, at 5993 0, at 6580 0, at
7085 stake for E. cor. of League 20, at 7100 a point 8 vs.
N. $45^{\circ} W$. of stake set for N. cor. of 19, which stake I moved
to intersection of lines, making $19 - 3558$ vs. wide.
Beginning at near north cor. of 19, thence S. $45^{\circ} W$. 18 vs.

to stake for East corner of League 20; thence N. $45^{\circ} 10'$.
at 678.20, at 1491.20, at 2020 set stake for a corner of J.
S. Pierre League, at 2162 x road, at 27690, at 3272 1/20 at
3500 n. set stake; Thence S. $45^{\circ} W.$ at 577.20, at 10620, at
13250, at 1623 1/20, at 1830 stake, at 20100, at 2083 x road,
at 25380, at 2946 1/20, at 3304 1/20 in East edge of Lake,
at 35400 in West edge of Lake 40300 (searched for miked
Hickory within a radius of 150 yards, could not find it.)
at 4388 x road, at 43910, at 4530 x fence into field, at
4984 x fence out of field, at 5151.80, at 5360 x road, at
5427 x road, at 54400 at 5545 x branch at 5760 x branch,
at 6628 n. stake set for upper cor of Lea. 20 is 21 n. to right.
Could find no traces of original bearings.

Beginning at stake set at 1830 n. in N.W. line of League
No. 20; thence S. $85^{\circ} W.$ at 689 1/20, at 976.70, at 1032 x small
branch, at 13400, at 16270, at 1946.60, at 23050, at 2417 x
road, at 32390 offset $83^{\circ} 1/10$ n. to right to middle of turn row
claimed by owner as lower line of San Pierre League,
at 3447 n. East edge of Navidad River, could find no
trace of orgl. bearings, River bears N. $79^{\circ} W.$ 640 to bend
Northward.

Beginning at the stake set by me for the East corner
of Mercer League; thence N. $45^{\circ} E.$ 800 n. thence South
at 87 n. a Post set for North corner of M. White Sur. bears
4 n. West at 2061 1/2 n. intersect N. line of G. Baker
16 3/10 n. West of an old Live Oak Stake set for the S.W.
corner of Survey No. 9 Block No. 3; thence N. $89^{\circ} 28' E.$
850.8 n. to a point; thence South 1356.7 set a hub0,
thence East 2152.8 n. set stake; thence South 253 n. set
stake; thence East at 1257 n. set stake for corner of
Heard Lea. 2752 n.0 Brimby Cr. 32 n. left, at 2762 come
back 13 n. left, at 2788 n. x Brimby Cr. (runs S. $8^{\circ} W.$ for

57 vs. then East for 50 vs. and then S. 56. 60 vs.) at 3026 vs.
to a stake. Thence South at 536 vs. bend in Brusley
Creek 26 vs. to right, at 597 vs. x Brusley 26 vs. East of
bend in same, at 782 re - cross same, at 854 x same
Creek, at 1961 x branch of Brusley, at 3776 x Sullivan's
branch, at 4400 hub, at 5200 o, at 6000 o, at 6800 o
at 7200 o, at 8379 x slough, at 8400 o, 8942 to a stake
on N. bank of Navidad River, fr. wh. an Ash 30" in dia.
bears S. 10° W. 4 vs. (bottomwood tragou).
^{83 37-2.}

Beginning at hub at end of course South ^{1344 R} 1356.7 near
S.E. corner of A. Baker; thence West at 40 vs. Sullivan's
branch is South 85 vs, at 100 vs. branch South 33 vs. at
234 vs. branch is South 51 vs. at 272 x branch, at 310 vs.
branch is North 30 vs., at 600 vs. o ^{1244 REC} 1341.2 vs. thence
South at 1344 vs. found no corner; at 1430 found
no corner; ^{5190-REC} 5280 North bank of Navidad found
no corner.

Beginning at a stake on N. bank of Navidad River
the lower corner of Peter White Lea. No. 17 fr. wh. a Box
Elder 20" in dia. bears N. 69° W. 2 vs. Thence North
along the West side of an old fence at 310 x branch
at 900 vs. cor of fence 10 vs. to right, at 1017 x road
and stripe marked line soon 15 years old, at 1441
vs. large P. O. for and a tree, at 3158 vs. x branch
at 3240 left timber, at 5857 x ⁵⁷³⁰ Sullivan's branch
at 8597 stake set by me at end of course South 253
vs. bears 6 vs. East.

Beginning at the stake set by me for corner of Heard
Leagu in N. line of Bowen Lea. at 1257 vs.;
thence North at 295 vs. x fence 55 vs. West of corner,
at 648.7 o, at 1703 o 67 1/2 vs. West of corner of fence
(running N. S. and E.) at 2049.3 o, at 2226 x Brusley Cr.
counter 27634

at 2064 v. set a stake, at 2046 $\frac{1}{2}$ 0; Thence West at
 240 v. x Brushy, 550 $\frac{2}{10}$ v. a point 2 v. North of a
 stake fr. wh. a L.O. 18" bears S. 61 $\frac{1}{2}$ E. 99 $\frac{1}{4}$ v. the orig.
 S.W. corner of Ed. Deaty. Returned to hub at 2046 $\frac{1}{2}$
 thence continued line same course and bound at
 3740.6 0, at 4408 x fence at 4420 $\frac{1}{2}$ 0; Thence West
 at 418 x Brushy br. at 528 v. 0 $\frac{1}{2}$ v. North of a
 stake set for N.W. cor. of Deaty fr. which a Live Oak
 30" in dia. S. 19 $\frac{1}{2}$ W. 92 $\frac{1}{2}$ v. Thence from 0 North
 at 35 v. x Brushy 508 $\frac{1}{2}$ v. set a stake; Thence West
 at 5330, at 555 L.O. 14" in dia. on E. bank of Brushy
 mked. \bar{x} is North 7 varas, at 558 x breach, 995 v. stake
 set for N.W. corner of Guthrie is North 12 $\frac{9}{10}$ v. fr.
 which stake a bunch of L.O. mked. \equiv bears N. 43° W.
 89 v.; at 1015 $\frac{4}{10}$ 0 5 $\frac{1}{2}$ v. North of cor. of fence, at
 1505 v. set a stake. Thence North at 494 v. x Brushy
 at 817 $\frac{1}{10}$ 0, 1950 v. set a stake; Thence West at 1029 0
 at 1118 v. a L.O. 12" in dia. mked. \times on S.E. side
 with nail in centre of \times and \equiv on South side is 12 $\frac{1}{2}$
 v. South, at 1131 v. x Brushy br. (marked live trees
 stop on East side of breach) at 1200 re-cross Brushy
 at 1383 cross again at 1520 v. bend in breach
 30 v. North, 1900 v. set a stake. Thence North
 at 709 v. 0, at 742 v. x Brushy, 1900 v. set a stake;
 Thence West at 1235 0, at 1392 a P.O. 14" in dia.
 mked. \bar{x} on E. & W. side with nails still in centre
 of each \times is 10 varas North, at 1493 v. x Brushy
 at 1725 breach 7 v. to the North, 1900 stake; Thence
 West (new bound) 421.70, 1358 $\frac{1}{2}$ x fence (n.t.) 1363 0
 Beginning at stake set by me on N.E. line of
 Whitaker at 2020 v. from its E. corner; Thence
 N. 85° E. 1725 v. set a stake; Thence N. 5° W. 1600 $\frac{6}{10}$

(4)

T. Jackson Co. Sta. Hill 46

Page 1126
1872

set hut \odot at intersection of line from N.W. cor of Tr. 3
Block 3 at 1398 $\frac{2}{10}$ W. from said corner; at 2692 \odot
3500 W. set a stake; Thence S. 85° W. at 770 W. set stake
3572 \odot (could not find blazed Black Jack) offset
N. 5° W. 69 $\frac{1}{4}$ W. to an old marked line which runs
S. 86° W., at 6209 x fence (running now S. 86° W.)
at 6515 x fence, at 6533 x road, at 6670 x road, at
6775 x Slough, at 7343 stake on Eastbank of Navidad
River, found no bearings. Went to stake set for N.E.
cor. of San Pierre and moved it 17 W. N. 5° W. to
where marked line from River N. 86° E. would inter-
sect. Thence S. 86° W. 770 W. and moved stake to this
point. Thence N. 4° W. at 1157.5 hut, 2500 W. set
stake; Thence S. 86° W. at 608.8 \odot , 1280 set stake, at
2182 W. \odot , at 5395 x bounty Road, at 6738 W. set stake
on E. bank of Navidad River, found no bearings.
Went to stake set at 1280 W. in last line and run
N. 4° W. at 789 \odot , 1500 W. set stake.

Beginning at a stake on E. bank of Navidad River
set for the S.W. corner of J. Scott (could not find
old bearings) thence with marked line and along
a fence at 541 x Lavaca and Jacks on E. line at 1370
x Road, at 2118 W. could not find bearings, 2805 W.
set a stake 78 W. South of a stake set for S.E. corner
of Scott, at 4453 point 108 $\frac{1}{2}$ W. N. 4° W. from stake
set at end of course N. 4° W. 1500 W. Moved stake to
intersection of lines, making the Madden Survey
1608 $\frac{1}{2}$ W. wide.

Returned to \odot set near Northline of Ed. Beatty Survey
at 4420 $\frac{1}{2}$ W. North of Northline of Bowen League.
thence North, same count, at 5286.5 \odot , at 6082.2 \odot ,
at 7408.7 \odot 1 $\frac{1}{2}$ W. South of fence; Thence East at 714

set hub \odot 8 vs. South of a stake set for the S. E. corner of
J. W. Jernigan fr. which stake a P.O. mtd. J.J. on South
side and \equiv on East side bears N. 2° W. 435 vs. Thence
from \odot South 206 vs. (or 214 vs. S. of stake) set a stake;
Thence East at 1344 vs. set a stake (could not find
bearings) at 1939 vs. set a stake about 30 vs. inside of
a thick timber, could not identify bearings or find
anything to correspond within 475 vs. radius,
at 2239 x Long Branch, at 2320 re - cross same,

at 2344 vs. set stake in heavy timber, could not
find bearings. Returned to stake set for S. E. corner
of Sur. 5 at 1344 East in last line; Thence North
at 840 vs. x creek at 1000 vs. set stake; Thence East
at 122 vs. a branch S. E. Made a print to fit calls
of creek but could not find bearings.

Returned to hub at 7408.7 on base line North and
continued course and found at 8073 \odot , at 8341 x
Long branch at 8394.2 \odot which is 259.5 vs. East of
a stake set for the N. W. corner of J. W. Jernigan
fr. wh. stake a L.O. 12" mtd. \equiv x \equiv as marks, bears
North 220 vs. Thence from hub at 8394.2 East
at 214 \odot at 555 x fence at 714 set stake for N. E.
corner of Jernigan, bearings gone.

Beginning at a stake the S. W. corner of Russell
Ward Survey fr. wh. a P.O. 28" bears S. $57\frac{1}{2}^{\circ}$ W. 55 vs. and
a P.O. stump 24" bears S. 42° W. 60 vs. Thence East
298 vs. to a stake for N. W. cor. of L. D. Cottle fr. wh. a
L.O. at point of timber bears N. 45° W. (Var. $8^{\circ} 15' 6''$)
a brushy L.O. in cluster of Post Oakes bears S. 80° W.
about 350 vs. and a bunch of small L.O. bears
S. 89° E. 300 vs. Thence S. 1° W. (or S. with Var. $8^{\circ} 15'$)
at 1650 vs. set stake for N. E. cor. of Highsmith, no

(6)

Jackson Co St. File # 60

005

bearings to be found, at 1750 x fence E.W. at 1945
marked line perhaps 20 years old $36\frac{1}{2}$ vs. to left,
at 2607 x Longbrandy, 2667 set a stake 50 vs. East
of stake set at end of course East 2344 vs.

Beginning at a stake the N.W. corner of James
Williams Survey; Thence S. $0^{\circ}45'$ W. with a marked
line at 330 vs. x Longbrandy, at 547 x prong of Long
brandy, at $1234\frac{1}{2}$ vs. \odot 59 $\frac{7}{10}$ vs. East of a stake set
for the S.E. corner Jos. Simons from which S.L.O. bears
S. 26° E. 185 vs. and an old L.O. stump in bunch of
small L.O. bears S. 35° W. about 500 vs. (Var $8^{\circ}15'$ for
bearings). Beg at the said stake at S.E. cor. of Simons
thence N. $89^{\circ}15'$ W. 1251 vs. set a stake for S.W. cor.
(bearings cannot be identified) Thence N. $0^{\circ}45'$ E.
at 506 x prong of Longbrandy, at 1531 vs. intersect
line run East 7 vs. East of stake set at 1939 vs. and
moved said stake to intersection or 1946 vs. East
of S.W. cor. of Survey 5.

Returned to S.E. cor. of Jos. Simons; thence South
at 862.5 put, at $1653\frac{1}{2}$ vs. set stake; thence East
at 732 \odot , 1464 vs. set stake, found no bearings.

Went to Stake set in base line 2364 vs. North of
beginning of same; thence East at 511.6 \odot , at $1495\frac{1}{2}$ \odot ,
at 2100.8 \odot , at 2630.5 \odot , at 3311 vs. stake; thence

North at 800 \odot , 1800 vs. set stake; thence East at
581 vs. intersect W. line of J. Williams Survey 163.5
vs. North of my stake set for his S.W. corner.

Returned to stake set at end of course East 3311 vs.
and continued course and found at 4209.5 \odot ,
at 5334 vs. set a stake which is 97 vs. North
and 44 vs. East of a bunch of marked Live Oaks
called for as bearings to the Wideman corner.

at 5798.40, at 6136.50, at 6392.50, at 64120. x
drain, at 6870 v. x another drain, at 6970 v. West
bank of Sandy brook, thence South 100 v. and East
55 v. to bank of brook. could not find bearings
nor any marked lines.

Beginning at the stake set by me for the N.E. corner of
the J. W. Jerrigan Survey; thence North 180 v. set a
stake; thence East at 1113 $\frac{1}{4}$ v. a stake set for the
S.W. corner of Lucy A. Jerrigan bears South $38 \frac{4}{10}$ v.

fr. wh. stake a Bl. J. 13" mkt. x old bears East 70 v.
at 1344 v. could find no bearings. Set stake for
N.E. corner of 5, $38 \frac{4}{10}$ v. South of last call.

Returned to hut in base line at 8394.2 and ran
North same count, at 8650 v.0, at 9424 $\frac{1}{2}$ 0, at 102050,
at 103130, thence West at 5120, at 10620, at 1750
x Longbranch (S.E.) at 17680 set 16 $\frac{1}{2}$ v. North of
a stake set for S.W. corner of Sur. 4 Bl. 2, fr. which
stake a Pin Oak 24" (now dead) on East side of
brook bears East 30 v. Thence (from 0) North
at 51 v. x Longbranch, at 271 v. a Live Oak 30" mkt.
x on East side of brook is 6 $\frac{6}{10}$ v. West, at 273 v. x
Longbranch, at 1400 v. re-cross Longbranch
at 1900 v. set stake.

Returned to hut on bench line at 10313, and ran North
old count at 10764.40, at 121970; thence East
at 1320 v. set stake, at 742 v. hut, at 11680, at 1578
x branch at 1615 re x same, at 1645 re x same, at
2014 x fence at 2032 v. set a stake. Thence East
(new count) at 282 v. a stake set for the N.W. corner
of J. R. Rogers Survey is South one (1) vara, at 317 $\frac{1}{2}$
v. set a stake fr. wh. a P. O. 15" $\frac{8}{10}$ on S. side bears N. 26 W.
103 v., at 993 v.0, at 1246 v. x fence 2 v. S. of corner

at 1267 vs. \odot , could not find original bearings.

Stake set at the cor. of fence aforesaid from which
a L.O. 20" x bears S. 30 W. 37 vs., at 1530.7 set hub \odot
6 1/2 vs. South of stake for S. E. cor. of Surr. 1 Pl. 4
fr. which stake on Southbank of Goldenrod Creek
a L.O. 4" bears N. 46° W. 3/5 va. a L.O. 4" S. 1 1/2 E. 3/5 va.
and a P.O. 10" N. 83 1/2° E. 4 vs.

Thence North at 9 vs. x creek at 514 1/2 vs. a P.O. 15" 3 vs. West
mkd. $\frac{x}{=}$, at 828 vs. a clump of 4 P.O. growing together
at roots mkd. $\frac{x}{=}$ are East 1 1/2 vs., at 1103.6 an old
stake and md. 2 vs. West, renewed Corner.

Thence West at 542 vs. \odot 3 8/10 vs. North of old stake
and mound, which renewed.

Returning to stake set for S. W. corner of Surr. 1 Pl. 4 at
end of course East 2032 vs. Thence North at
534 \odot , at 1356.7 \odot , at 2284 \odot , at 2925 \odot , at 3027 1/2 \odot ,
38 vs. East of an old Stake which renewed for the
N. W. cor. of Surr. 1 Pl. 4; Thence East at 780 vs. stake
set for cor. of surr. 1 in S. W. line of Etheridge
Surr. fr. wh. a forked L.O. 20" bears N. 1 1/2° E. 47 vs. a Pl. J.
10" bears S. 57 3/4° E. 13 vs. Thence S. 60° E. at 225 vs.
a stake set for the N. E. cor. of Surr. 1 Pl. 4 is 2 vs. to
left, fr. wh. a L.O. 24" bears N. 65 3/4° W. 42 vs. a do. 10" S. 35 1/2° W.
32 1/2 vs. Returns to hub set at 3027 1/2 vs. and continues line
North, some burnt, at 3368 vs. x road, at 3477.7 at \odot S. 60 E.
44. vs. from a stake set for the N. E. cor. of Surr. 21 Pl. 1
fr. wh. stake a L.O. 24" bears S. 5 1/2° W. 24.8 vs. P.O. bearing
gone. Thence N. 60° W. at 990 vs. \odot , at 1060 \odot , 4 vs. N. 30 E.
from an old st. & md. from which stake a Pl. J. 10" N. 63 1/2 W.
189 1/2 vs. a L.O. 4" N. 24 1/2 W. 23 1/4 vs. (a corner of surr. 21)
continue same course and burnt at 1169 vs. set hub
N. 30° E. 4 6/10 vs. from old stake & md. for W. corner of

J. M. Harlan sur. fr. wh. stake a L.O. 6" bears N. 16³/₄° E. 94
 vs. and a Pl. J. 15" N. 57³/₄° W. 81 vs. Thence N. 30° E. at
 213 vs. set a 12¹/₂ vs. N. 60° W. of a stake set for the South
 corner of P. Daugherty sur. fr. wh. stake a 4 pronged L.O.
 20" \bar{x} bears S. 63° W. 20¹/₄ vs. a do. 6" N. 54° W. 5⁹/₁₀ vs.
 Returned to a set N. 30° E. 4⁶/₁₀ from W. corner of
 Harlan; thence prolonged line N. 60° W. at 1305 vs. x
 branch, at 1511 vs. a, at 1645 vs. x road, at 2117.8 vs. a
 Thence N. 30° E. at 205.6 vs. old stake & md. for W. cor.
 of P. Daugherty sur. is 2⁶/₁₀ vs. to left, at 464⁷/₁₀ vs.
 set a 5 vs. West of a stake set for the N.E. corner of the
 G. Elley survey fr. wh. stake a Pl. J. 10" bears S. 71¹/₂° W.
 10¹/₄ vs. a Pl. J. 15" N. 82° E. 12¹/₄ vs. a do. 10" N. 15° E. 28³/₁₀ vs.
 Thence West at 5 vs. pass corner of Elley, at 281 vs. the
 26th mile post on bounty line bears North 90 vs. at
 577 vs. set a North 5¹/₂ vs. fr. old stake & md. a corner
 of Elley's survey. Thence North at 239 vs. x Road
 at 1087 vs. set a 1²/₁₀ vs. West of an old stake & md. for
 cor. of Elley sur. fr. wh. stake a Pl. J. 15" bears S. 58¹/₂° E.
 190¹/₂ vs. a do. 12" S. 44¹/₂° E. 174³/₄ vs.
 Thence West at 16 vs. a st. & md. bears North 10 vs. at
 565 vs. x drain, 1684 vs. a, at 2503 vs. a, at 3429.6
 old stake & md. North 35.7 vs. set for S.W. cor. of Whitney
 at 3672 vs. set put S. 5° E. 16¹/₂ vs. from an old stake
 & md. for N.W. corner of G. Elley survey; Thence S. 5° E.
 at 222 vs. an old stake & mound set for the N.W. corner
 of sur. 14 Pl. 1 bears East 40.8 vs., at 503 vs. an old
 st. & md. the S.E. corner of White Lea. is one rod East,
 at 562¹/₂ vs. a, at 972²/₁₀ vs. a 24 vs. East on an
 old mound with stake set for the N.E. corner of
 Survey 13 Block 1. Thence West, at 24 vs. pass over
 old st. & md., at 105 vs. x head of Longbranch, at

794.7 n. o, at 1577 n. point 45 vs. South of corner of farm,
at 1978 o, at 2050 Cr. 3 vs. N. at 2086 vs. Large Live Oak
5 1/2 feet in dia \bar{x} is North 37 vs. at 2692 vs. x road
at 2937 n. o, at 3440 old stake, mid. the N. W.
corner of Survey 8 Bl. 1 is South 30 vs., at 4369 n. o,
4895 was set a stake fr. wh. a large L. O. N. 23 E. about
1200 n. and the 10th mile post on Lavaca and Jackson
county line bears N. 20 E. about same distance
Thence S. 85° W. 1598 n. intersect county line, could
not find 11th mile post.

Returned to stake set at end of course West 4895 vs.
and ran S. 5° E. 1180 n. set a stake; Thence S. 85° W.
875 vs. o, at 1703 1/2 vs. o, at 2082 o, 3096 w. set a
stake; Thence S. 5° E. at 313 1/2 vs. o, at 915 vs. o 1299 1/10
intersect my northline of Madden 30 6/10 vs. S. 86° W.
from stake set by me at 2805 vs. from River for the
S. E. corner of Scott.

I, P. P. Putnam, County Surveyor of Jackson
County do hereby certify that the foregoing
lines were actually run on the ground, and
that I have examined the field notes thereof
and find them correct and that they are recorded in my office in Book C, Pages
34, 35, 36, 37, 38, 39, 40
and 41.

Given under my hand and this
7th day of August - A. D. 1894

P. P. Putnam,

County Surveyor Jackson County.
Tex. Co.

The foregoing preliminary survey was made to determine the locations of surrounding the Blocks of I. G. N. R. R. Co. surveys, and also to locate older claims inside of said Blocks.

The survey shows that the upper corner of the Eli Merer League is $N. 34^{\circ} 48' W. 3614$ rods from the lower corner. The North corner of the J. M. White League is a recognized point and found to be $N. 45^{\circ} 24' E. 8475$ ^{from the S.W. cor. of Merer.} rods, in locating

the boundaries of the Merer, Whitaker and Pierre Leagues, this course was adopted and the preliminary survey was turned upon its identified corners 24 minutes to the East. No original corners could be found for the A. Baker 320 acre survey and it was located according to the calls for crossings of Lutherland Creek for which purpose the creek was located at several points along the Southline of the Baker and the West line of same. The creek crosses the Baker Southline 283 rods West of the S. E. corner as located by me and marked by an iron pipe as per corrected field notes of Survey 10 Block 3.

It will be seen that by the preliminary survey Boushy creek does not cross the North and East line of the Bowen League at the proper distance. It was found that if the Bowen and White Leagues are turned $1/2$ degree to the East on their River corners as found, the crossings of Boushy would fit very closely, as would also the crossing of Lutherland Creek through the Baker Survey. This was done and the courses of $S. 89 1/2^{\circ} E.$ and $N. 1/2^{\circ} E.$ were adopted for the adjoining I. G. N. surveys.

Tabor Co. St. Pl. # 6a

DC 11

After the aforesaid preliminary survey was completed a marked line was found parallel with my new Northline of the S. Bowen League, 21.6 ^{vs.} North of same, and as said line, although farther North than it ought to be, was recognized as the correct line by the surveyor ^(Christy) who was subdividing the Heard League, I adopted it in my own survey.

In the re-^{construction} and correction of the I. G. N. R.R. Co. Blocks, the following original corners and calls have been respected and the different surveys constructed accordingly.

1. The lower corner of Patrick Scott on Navidad River
2. The lower cor. of Samuel Cham " " " determined by old marked line.
3. The upper corner of Eli Mener Lea. on River
4. " lower " " " " "
5. The North cor. of John McWhite's Sur.
6. The S.W. corner of sur. 9 Bl. 3, I. G. N. R.R. Co.
7. The A. Baker sur. by crossings of creeks
8. The upper corner of Sylvester Bowen on River
9. The N.E. corner of " " " by creek crossings
10. The lower corner of " " " on River
11. The S.W. corner of W. J. Wickam
12. The S.W. corner of Ed. Beaty
13. The N.W. corner of Ed. Beaty
14. Tree in Northline of Rob. Guthrie
15. " " " " Sur. 5 Bl. 3, I. G. N. R.R. Co.
16. " " " " " 3 " 3 " " "
17. The N.W. corner of J.W. Jennigan's survey
18. " S.E. " " " "
19. " The S.E. cor. of Jos. Linn's survey

Jackson Co. Sh. File # 60

20. The S.W. corner of Lucy A. Jennigan's Survey
21. Tree in Southline of surr. 4 Block 4
22. corners of surr. 21 Bl. 1 on S.W. lines of Preemptions
23. " " " 1 Bl. 4 near Martin Co. line
24. N.W. Corner of surr. 14 Bl. 1 J. G. N. R. R. Co.
25. N.E. corner " 10 " 1 "
26. N.W. " " 8 " 1 "
27. S.E. cor. of John S. Scott survey.

Upon the foregoing identified corners the J. G. N. R. R. Co. surveys were re-constructed with strict adherence to the calls in the patents, and the configuration of every survey was retained except in the base of survey 12 Block 3 which had to be extended West of the Realty to retain its quantity.

One hundred Iron pipes each 3 feet long by 1 1/2" in diameter marked with the numbers of Blocks and Surveys were planted at most prominent corners, and other corners were marked by bois d'arc stakes also bearing numbers of Block and Survey.

Recorded in my office in Book C Pages 41, 42, and 43.

August 7th 1894 P. P. Putnam, County Surveyor
Jackson County, Texas

File: 6^a

Jackson County.

Filed in the Gen^l Land
Office August 27/94.

W. L. McGeough

Commissioner.

ppputman's connecting line be-
ginning at S. Cor. of Eli Maner
league.

Dated Aug. 7, 1894.
Filed Aug. 27, 1894.

(15)

OC 14

count 27698