

New Caney, Rexas, Jan 10, 1934 RECEIVED

JAN 75 1934

Montgomery Co.

Hon. J. H. Walker, Com Gen Land Office Austin, Texas

Dear Sir:

P

REFERRED TO MAP

2438

Have delayed writing you for the past year, thinking that during this oil rush here I would come to Austin, but have not and don't seem that I will at this time as the rush is about over. Just completed making a location for a well on the Pryor Bryan, this being a wild-cat well about 10 miles from the field.

Will you kindly mail me blank affidavits for me to make out in filing my application for a license.

Second: --- a strip of land 960.5 vrs long and 377.3 vrs wide either in the M B Jackson or excess land. As I wrote you before I was out there about two weeks in December, 1932, being a little more than a year ago and surveyed out the Wyatt Anderson. The maak lines indicate where the survey was then located. I moved it east 377.3xixx vrs. The red lines indicate where I left the survey. I notified adjoining owners, but they never answered me. Just recently I saw the owners, the Herrens, of the M B Jackson that join this strip of the west. They said they did not own it and would not claim it; that they had been with many surveyors. Burns, Gillespie, et al, and was satisfied they did not own it. I told them some of those surveyors, not all had placed the Anderson where it has been since about 1886 and they called that right, and I say that it is wrong. So I have taken the not ter up with them, and they don't seem to think they own it, and so I am now advising you. This is what Indene. I started at "b" this corner being known as the SW corner of Thos Miller and NW cor of John R Copeland; thence south and west to the river and found I was short 377.3 vrs. I then comes back according to the patents, 1000 vrs, 64 vrs and 1837, which is a little more than is mentioned in patent of Wm Vince and fine that I am at the NE cor of Wm Vince, whichmeans that line was measured and compassed twice: I go thence around until I get to North line of Anderson, runsternorary line first;; then makes permanent line, both have the same measurement; that means that course East and west measured four times, andon. I was double careful to do the work right, as I was sure a law-suit would be next, and it is just about to come off now. One injunction has alredy been completed. You will note that the 1240 vrs line in the extreme SE corner of Anderson stops at Wm Vince line; that the extreme west line of the Anderson stops at the vertical ine on the least of the Allen Vince; It seems to me that was done intentionally and that the surveyor knew it was wrong.

The two little squares on the east end of the Anderson: 414 by 377.3 vrs has been patented twice, first to Anderson; then to Cax Copeland; the 551.3 by 377.3 was first patented to Anderson, and later patented to Thos Miller. "b" isw-here Madeley - A.M. Your file SF 13363, began all his surveying est, and all his work is wrong. His surveyor, Mr. Hall of New Waverly recently done some surveying out there and used that same point, "b" for beginning, and that is wrong. You will not that part is well Janmed. The Harrison is over on the James 22 526.4 vrs, and the August V Sharp is against the Harrison, a lot of moving to do. However the State has same sold some land, one sale was to T L Roberts about 20 years ago,? and if this is first ever straightened out he and some of those last ones near him to buy, will lose. By referring to your ed map. yu u willnote there is a small vacancy in the vicinity of the east and south lines the AV Sharp, and when the Harrison and Sharp are moved east this 526.4 vrs, it will take up some of that excess. I have notified the owner in the Janes and Harrison about this. He seemd to think the State ought to straighten it out. I told him that was up to him that he should have surveyed it out when he bought it. If he has ever done anything about it, I have not been told about it.

You willnote that the present same and the Anderson XXXX NW corner of the Anderson is near the Bar_clay corner. I can't advise what effect this work will have on that survey, or whether this excess 377.3 vrs by 960.5 vrs goes for ther or not Math.

Now, if you should want to know about that, I think Iam entitled to the job, and could do he work in less time than a new surveyor. The Jackson and the John Owens would have to be run out, and the measurements east and west of the river should definitely determine whether this excess is there, or whether it is a part of the Jackson. The Herrens state they have measured it with about six surveyors, and that their b ast line is right as it has been all their life and at present, and that they do not own it.

You may think variation has had something to do with this, but not, that part is **Dependentings** all right, the magnetic variation of all lines I have run out there was six degrees, and all lines almost perfectly straight.

As to figuring out where the Copelands and A M Madeley are going to get their land: That is a very hard task. I am informed that the brother of Mr. Madeley is now trying to get this subject to moving again. Mr. Hallshould have gone down to the Geo Mason line to get begin, but he did not. He went no farther south than the present old line of the Harrison. That is what A M Madeley told me himself about two weeks before he died.

Again reminding you of the blanks for license, as I have several subjects in this letter.

Yours very truly,

C L Reinhardt C. L. Rein hardt

counter 31858

-2-

Sketch File No. 21 Montgomery County sketch& statement by S.L. Reinhardt Recd. January 15th 1934 J. H. Walker, Comm. menter 31859 C.F. Blucher File Clerk Descriptive: Vicinity Wya H. Anderson 13. Mi 5.35° E. Conrae. "For what it maybe worth "