(#2345)

M. D. Rawls

LICENSED STATE LAND SURVEYOR & COUNTY SURVEYOR, STERLING COUNTY PHONE 200 P. O. BOX 533

STERLING CITY. TEXAS June 20th, 1955.

RECEIVED JUL 26 1955 GENERAL LAND OFFICE

1-315

Commissioner General Land Office Austin, Texas.

> REPORT OF RESURVEY of T. & P. Ry. Co. Blks. 31, 32 and 33, Township 5 South, and part of Block 22, H. & T. C. Ry. Company. Sterling & Glasscock Counties.

Dear Sir:

GENERAL LAND OFFICE

JUN 22

1955

The following is a report of a resurvey made during the last 18 months for the J. L. Glass Estate, David Glass, Foster & Hildebrand, and others in the captioned blocks.

The original survey of the T. & P. Blocks 31, 32 and 33, Township 5 South, was made in 1875 - 1876 on the block and township lines only, by Surveyors Powell, Peck and Harris, working concurrently and each endeavouring to correlate his work with that of the other two surveyors.

In the particular vicinity covered by my resurvey. Powell ran the East line of Block 31, the South line of Blocks 31, 32, 33, and the West line of Block 32. Harris surveyed the North line of Block 31, and the East 3 miles of the North line of Block 32 of both Townships 4 and 5 South. Also Harris ran the North 4 miles of the East line of Block 32, and Powell ran the South 4 miles of the same East line. Peck surveyed the North, East and West lines of Block 33. This information is from the original field books used by the surveyors, and photographs of the books are on file in the Land Office.

In tying their work together, it was discovered that the lines of Peck and Powell were some 269 varas apart in latitude at the Southwest corner of Block 32.

counter 37184

2

nout

10-315

RECEIVED

JUL 26 1955

GENERAL LAND OFFICE

1-nietad

counter 37185

M. D. Rawls

LICENSED STATE LAND SURVEYOR a county surveyor, sterling county PHONE 200 P. O. BOX 533

STERLING CITY, TEXAS

Page 2 Report of Resurvey

· · · · ·

The records show that Powell ran a check line along the West side of Block 32, from the center line of the railroad location to the Southwest corner of 32, to verify Peck's work, and also his own. This check line was later used when writing the field notes of the Surveys along this block line.

While making this check, Powell ran about three miles easterly along the North line of Block 32, Tsp. 4 South, with the very evident intention of establishing the position on the ground of the Harris corners. Powell made this note in his book "at 765[±] varas intersection South line 46, 541 varas West from Southeast corner". After verifying his own corner at the Southwest of Block 32, Township 5 South, he surely realized that Harris was some 500 varas too far West with his work. Further, his recognition of the discrepancy is indicated by the fact that even though Harris surveyed the East part of Block 32, T 4 S, Powell wrote the field notes for the entire South half of Block 32, T 4 S, trying to correct the error by using his check line instead of Harris' survey.

The error in the Harris position has been recognized by several surveyors, but they have never submitted sufficient evidence, at one time, to allow the Land Office to make a definite decision as to what should be done to remedy it. Reference is made to maps and reports of Surveyors Beckett and Kellis, also of H. L. George.

My resurvey of the captioned blocks has been made to obtain proof that the construction of them was not irregular, but a uniform system of Surveys; and to relieve affected property owners of the uncertainty of the location of their section lines, caused by Harris' error in position. A similar error in Harris' work was found and corrected in Block T, T. & P. Ry. Company, Sterling County.

- refers to \$ 46 Bikso W+NW RRSM

2

M. D. Rawls LICENSED STATE LAND SURVEYOR & COUNTY SURVEYOR, STERLING COUNTY PHONE 200 P. O. BOX 533

STERLING CITY, TEXAS

Page 3 Report of Resurvey

2 . .

The South line of Township 5 South is well monumented and reasonably regular. The original corners with bearings made by Powell on the East line of Block 31, T 5 S, were found to be in an excellent state of preservation due to the fact that, since they are partly in conflict with senior blocks, no fence has ever been erected along this East line. I have found no evidence that these corners have been recovered before, except perhaps by Harris when he wrote corrected field notes for this area in February, 1879.

Along the East line of Block 32, T 5 S, no original corners were found by me except indirectly. A stone mound at the Southeast corner of the block recovered by Surveyor Kellis while bearings were still standing, and three miles up from it a stone mound was found, built in the same manner as Powell's other stone mounds. This corner was first recovered by H. B. Tarver during a survey made by him in September, 1886, and set forth in his report which is on file in the Land Office.

Along the West line of Block 32, T 5 S, the Northwest and Southwest corners were the only original corners found by me. There is evidence by dependable witnesses that the other corners along this line were wilfully destroyed in the past by a former property owner, now deceased. The resurvey corners of Surveyors J. A. Simpson and W. F. Kellis are on the ground.

On the North line of Block 33, T 5 S, eight original corners were found. The original Northwest and Southwest corners of Block 33, T 5 S, also were recovered. No original corners between these two were found by me, but I did find the resurvey corners of Surveyors J. A. Simpson and J. E. Beavers. The resurvey of J. E. Beavers was made in 1910 while some of the bearing trees were still standing, and part of his corners are identified by him as original.

counter 37186

A-315

M. D. Rawls LICENSED STATE LAND SURVEYOR & COUNTY SURVEYOR, STERLING COUNTY PHONE 200 P. O. BOX 533

STERLING CITY, TEXAS

Page 4 Report of Resurvey

Using the original and resurvey corners set forth in the preceeding paragraphs, I have reconstructed Blocks 31, 32, and 33, T 5 S, following the footsteps and intentions of the original surveyors, as a uniform and homogeneous system of Surveys.

The part of Block 22, H. & T. C. Ry. Company resurveyed by me has been constructed from the corners set by the original surveyor, Jacobo DeCordova, in May, 1867, and the resurvey corners made by Geo. Williams in October, 1906. For the location of these corners please refer to my map and the map of Mr. Williams on file in the General Land Office.

The corners of all Surveys belonging to my clients have been established with a marked 2" galvanized iron pipe set in concrete in a stone mound, and tied to the State Co-ordinate System. Also, the courses and declination used in field notes and shown on map are on the Lambert Grid, Central Zone. A total of 25 separate closures was made during this resurvey in order to obtain maximum accuracy.

Trusting that this report and other data will enable you to approve my work as set out in your letter to me of July 13th, 1954, I am

Very truly yours

man Parken

marpand

Stor. Go. Surveyor counter 37187

0-315

Filed in Sterling Go. Surveyors Records. June 13, 1955.

THE STATE OF TEXAS COUNTY OF GLASSCOCK

I, MRS. VENA LAWSON, Clerk of the County Court in and for said

Cou	nty, do hereby certify	that the	foregoing inst	rument da	ted the	20 day	of Jur)e
	5 with its certificates							
ė	July	19 55	at 4:30	o'clock	P M., an	d duly Reco	orded the .	ll day
of	July	19 55	at 10:00	o'clock	A M., in	Field	Notes	Record of
	County, in Vol.				· · · · ·			

WITNESS my hand and the seal of County Court of said County, at office in Garden City, Texas, the day and year last above written.

> preceeding paragraphs. I have recon is 31, 32, and 33, 1 5 5, following

Janzo Clerk

counter 37186

STECK-AUSTIN

By

340

__ Deputy

County Court, Glasscock County, Texas

52 County 3 uno COUN 2 part of resurve, 150 5% R.R. BIKS. ET.C.R.R 95 D. Raw JSSCOCK SNO ed' 20. 5 Rell 5 File No. Filed 012 0 By U 5

E