

LOCATION MAP (N.T.S.)





PLAT REVISED OCTOBER 4, 2005 TO REFLECT MEAN HIGHER HIGH WATER

FILE NAME: 050614m1



1. BEARINGS BASED ON TEXAS COORDINATE SYSTEM, SOUTH CENTRAL NAD 83.

2. MEAN HIGHER HIGH WATER AS SHOWN WAS ESTABLISHED FROM TIDAL BENCH

NOTICE: THIS SURVEY WAS PERFORMED IN ACCORDANCE WITH SECTION 33.136, NATIONAL RESOURCES CODE, FOR THE PURPOSE OF EVIDENCING THE LOCATION OF THE SHORELINE IN THE AREA DEPICTED ON THIS SURVEY, AS THAT SHORELINE

ARANSAS CO. 33.136 SKETCH 4

COUNTER 83353



urveying & Engineerin

August 3, 2005

Mr. Jerry Patterson Commissioner of Texas General Land Office 1700 North Congress Avenue, Room 812 Austin, Texas 78701 C/o Mr. Ben Thomson Director of Surveying

Re: Shoreline survey - San Jose Island

Dear Ben,

I am herewith enclosing a shoreline survey adjacent to the harbor and boat docks of Bass Enterprises on San Jose Island adjacent to Aransas Bay. This survey was at the request of Heidi Cyr, Assets Inspections, Texas General Land Office, Corpus Christi, in conjunction with Coastal Easement No. CE810079. Her inspection concluded that there has been more than five (5) square feet per linear foot of the affected shoreline of unnatural accretion due to the breakwater and harbor facilities.

The last known mean higher high water survey, to my knowledge, was a 1971 survey by Claunch and Associates filed with the General Land Office. In reconstructing the Claunch survey and running the current mean higher high water line, it was determined that there has been accretion of approximately 43,105 square feet on the northeasterly side of the breakwater and significant erosion on the southwesterly side of the breakwater.

I am requesting approval of the subject shoreline boundary pursuant to Sec. 33.136, Natural Resources Code, V.T.C.A.

Sincerely,

J. L. Brundrett, Jr., R.P.L.S. Reg. No. 2133 Aransas County Surveyor

Enclosures





P. O. Box 2322 Rockport, Texas 78381-2322 Ph. (361)729-6479 Fax (361)729-7933 jerryb@gbsurveyor.com www.gbsurveyor.com



# GENERAL LAND OFFICE

JERRY PATTERSON, COMMISSIONER

August 9, 2004

30361

-	and the same and the same
	AUG 1 1 2004
	Marin State

Sid R. Bass, Inc. c/o Mr. Herrell Flynt Bass Enterprises Production Co. 201 Main Street Fort Worth, TX 76102-3131

Re: Coastal Public Lands Easement No. CE810079 San Jose Island, Latitude 27°57'13", Longitude 96°59'20", being part of the 32,000 acres, more or less, described in deed recorded in Volume L4, Pages 539-542, in the Office of the County Clerk of Aransas County, Texas

Dear Mr. Flynt:

As we discussed on the telephone on August 9, 2004, the jetties authorized in CE810079 have caused significant unnatural build-up. In accordance with the rules set forth in the Texas Administrative Code for groins, Title 31.4.155A§155.3g.7C(iii) states "no unnatural accumulation resulting in the deposition of sediments greater than five square feet per linear foot of the affected shoreline". During the site visit on March 3, 2004, and review of the 2002 aerial photos, it has been determined that there is more unnatural build-up on site than five square feet per linear foot.

We understand the structures may be necessary for the continued operation of your facilities. Therefore, in accordance with Title 31.4.155A§155.3g.7C(v) of the Texas Administrative Code, they may be kept but "the boundary between State-owned submerged land and the adjacent littoral property must be established by a Licensed State Land Surveyor" (LSLS). As your county contains a county surveyor, Mr. Brundrett, his services may be used as well.

Alternatively, you may remove a portion of the jetties adjacent to the shoreline to allow the natural sediment transport patterns to re-establish. This alternative may cause the basin to silt in; thereby requiring maintenance dredging.

If I can be of further assistance, please contact me at (361) 825-3039.

Sincerely, Heidi Cyr

Coastal Biologist Asset Inspections

TEXAS GENERAL LAND OFFICE Art. 33.136, Natural Resources Code No. 4-B Co. Aransas File Date 10-10-2005 by \_\_\_\_\_

Asset Inspections – Lower Coast Field Office 6300 Ocean Drive • NRC Building, Suite 2400 • Corpus Christi, Texas 78412-5599 Phone: 361-825-3030 • Fax: 361-825-3040 www.glo.state.tx.us

COUNTER

83355

GENERAL LAND OFFICE NOTICE OF APPROVAL OF COASTAL BOUNDARY SURVEY

Pursuant to §33.136 of the Natural Resources Code, notice is hereby given that Jerry Patterson. Commissioner of the General Land Office, approved a coastal boundary survey, Aransas County NRC Art.33.136 Sketch No. 4, submitted by J.L. Brundrett, Jr., an Aransas County Surveyor, conducted in March 2005, locating the following shoreline boundary:

A survey of a portion of the MHHW Line of Aransas Bay adjacent to San Jose Island Ranch Boat House.

For a copy of this survey contact Archives & Records, Texas General Land Office at 512-463-5277.

Published Morch 15822, 2006

# TEXAS GENERAL LAND OFFICE Art. 33.136, Natural Resources Code Co. <u>Aransas</u>, No. <u>4</u> File Date <u>4-13-2016by</u> DJ-H

Alth: Yolanda Donzales Hi Yolanda-The cost to tun in the 3/15 & 3/22 issues will be \$ 55.64. Shanks, Kim Drue Rockport Pilot

<< Prev Document

## **Texas Register**

Next Document>>

AGENCY General Land Office ISSUE 03/10/2006 ACTION Miscellaneous

### Notice of Approval of Coastal Boundary Survey

Pursuant to §33.136 of the Natural Resources Code, notice is hereby given that Jerry Patterson, Commissioner of the General Land Office, approved a **coastal boundary survey**, Aransas County NRC Art.33.136 Sketch No. 4, submitted by J. L. Brundrett, Jr., an Aransas County Surveyor, conducted in March 2005, locating the following shoreline boundary:

A survey of a portion of the MHHW Line of Aransas Bay adjacent to San Jose Island Ranch Boat House.

For a copy of this survey, contact Archives & Records, Texas General Land Office at (512) 463-5277.

## TRD-200601195

Larry L. Laine

Chief Clerk, Deputy Land Commissioner

General Land Office

Filed: March 1, 2006

Re-Query Register Database Back to List

Co. Aransas, No. 4

File Date 4-13-2016 by DJH