

The State of Texas & W. J. Westmoreland
County of Childress } Surveyor of Childress County,
do hereby certify that the
following connecting lines in Childress
County were actually made on the ground
and that all marks both natural and
artificial are truly described and that
all distances were carefully made.
The following composing the party
assisting Mr. Sam. L. Chalk. (Custodian)
Hurt Mundy & Henry Gordon, Chairman
Malcom Black & Wm Whitehead (Flagman)
June 22nd 1896.

Beginning at a rock and
the S. E. corner of Survey No 182 B. S & F.
find the old bearings correct and
plainly marked.

Thence East (Va. $9^{\circ}40'E$) over rolling
prairie at 1952 vrs a point 14 vrs North
from a stone mound the S. W corner
of Sur. No 1. B. S & F. (found old bearing
correct) Change Va to $8^{\circ}59'E$.

Beginning at last above described
stone mound the S. W cor Sur. No 1
thence North 1900 vrs a point from
which we searched diligently without
finding the corner as described in
field notes of Sur. No 1. Crossing of
creeks correct.

We returned and began again at the
S. W corner of Sur. No 1.

Thence East at 1285 vrs a branch (S) at 1900
a point for S. W corner No 2.

Thence East at 300 vrs cross branch
at 2008 vrs a point 7 vrs North of the
S. W corner Sur No 3. Found old corner

as described in field notes.

Thence East at 60 vrs cross branch 1772 vrs
cross Bayler creek at 1961 vrs a point
at which we set an iron pipe which is
128 vrs East and 60 vrs South from Bayler
creek and 130 vrs west from a branch
all of which are called for in original
field notes.

Thence East from said Iron Pipe at 120
vrs cross branch about 20 vrs south of
junction with Bayler creek at 2103 vrs
a point.

Thence North at 520 vrs cross branch (N 200)
at 1874 vrs cross Bayler creek at 194 vrs
a point on South bank of branch 100 vrs
West of Bayler creek for the N.W. cor. No 5 -
A B + M. We believe this to be the corner as
there is no other place at which the crossing
on creek and position on branch can be
found. We believe the distance South from
the corner should be 66 vrs instead of
660 vrs.

Thence East from the last described point
at 100 vrs cross Bayler creek at 190 vrs a
point. Could not find stone mound.

Thence East 190 vrs a point.

Thence East 1900 vrs a point for N.E. corner
No 7. B. S + F.

Begin again at the Common Corner Surveys
No 45, 46, 47 + 48 A B + M. Found rock mnd.
and Coll. Stone bearing (plainly marked)
as called for in field notes.

Thence North at 9113 vrs a point 136 vrs East
of the common North corner Sur. No 7 + 8, as
located by us.



Thence East 1900 vs put in rock mound
for N. E. cor no 8 B. S. & F.

Thence North 5700 vs S. W. corner of
no 164 B. S. & F.

Thence North 1175 vs ^{on the base of no 682 B. S. & F. W. Ry Co} a point, Coulter
North at 1900 vs put in Iron pipe for
N. W. cor no 164 + S. W. cor no 163 B. S. & F.

Thence East 2335 vs a point 140 vs south
of an Iron Pipe (mtd 32) the S. W. corner of
Sur no 32 F. P. Stone.

Change Va. to $10^{\circ} 40' E$.

Thence North 3909 vs an Iron pipe mtd.
32 + 32 on S. B. Red River.

Begin again at the N. W. cor. no 35 Stone
at a point in river bra from which a pile
of rocks on side of bluff brs $S 85\frac{1}{2}^{\circ} E. 12$ vs
one mtd N.

Thence North 276 vs a point

Thence East 2850 vs the N. W. cor of Sur no 164
+ S. W. cor Sur no 163 B. S. & F.

Surveyed June 22-25th 1896

Hurt Mundy Chain
Henry Gordon Miner.

June 26th 1896

Beginning at a point on north
bank of Red River from which a Stake B.
on prong of Gardens Creek. brs N 46 vs
which we think is the place for the S. E. cor
no 22 S. P. Ry Co. The location is peculiar
and we found no other that would suit

Thence N 74 E 988 vs along bluff of river.

Thence N 70 E 1008 vs along bank of river.

Thence East 950 vs a point for S. E. corner
of Sur no 19 S. P. Ry Co. Something like an
old channel of Red River is along our course
also an old channel that appears to be that

Filed for record July 1 1896 at 11 o'clock A.M. + recorded same day in Book & pages 100-104
N. J. Westmoreland Surveyor
-15-
Childers Co

of Myracks creek has its mouth about 300
vs East of our point for S. E. cor No 19.
This is a low sandy valley of Red River
and the banks are constantly changing.
Thence East from above point at 2365 vs
cross Myracks or Salt Creek at 3320 vs we
re-cross the present channel of Myracks cr
about 450 vs above mouth, at 4997 vs a
point. Thence South at 5530 vs a point
Thence East 277 vs a point 53 vs north from
an iron pipe for the S. E. cor No 60 + S.W. cor
No 61 F. P. Smith. Continue East at 1372 vs a pt.
Thence South at 947 vs a point. Thence East
213 vs. Thence South 153 vs a Cotton Wood
which appears to be marked on East and
West side which we think is the S. E. Cor
No 18 S. P. Ry Co. This tree is the most westerly
one of two on bank of river and very much
exposed to wind + sand. The marks are
not very distinct but were evidently
made by a surveyor.

Surveyed June 26 + 29 1896

Heart Mundy Chain
Henry Brown Iron
N. J. Westmoreland Surveyor
Childers County - Texas

Before me the undersigned authority, this
day personally appeared Sam L. Chalk
who after being duly sworn deposes and
says that in assistance in the above surveys
and believe the above statements to be
true + correct

Sam L. Chalk

Subscribed + Sworn to before me on this the
1st day of July 1896

W. L. H. Dutton
Notary Public in and for
Childers County Texas



Counter 18381

July 8/96

Connecting Line of Surveyor of Childers Co. filed in General Land Office