

I hereby certify that this sketch was made from actual survey and that the red lines and distance in red figures actually run and the bearings thereon marked are as the ground.

J. W. Ratchford
 Co Surveyor Rancho Co Tex

Aug 23rd 1887.

MS 10° 10' E 19. Old marks
 This stump standing here
 cut down within past 12
 months, has old marks

Aug 27th 1887

Coaster 19134

Sketch file N^o 8.1/2
Concho Co.

Filed Aug 24/87.

R. Sherry
Chief Clerk.

Counter 19135

According to this connecting line
The E cor of No 618 is 11 to S + 8 to
E from NW cor of No 23, & necessarily
in conflict with No 2 T. B. R. Co.
No 22 will conflict with
No 617 as well as with No 1
T. B. R. Co. No 14 will conflict
with No 1 NW + SE 22 1/2 pts
& No 15 with said No 1 & also
with B. Gage D. 17 1/2 pts
Aug 29/87 Hill

N

THE STATE OF TEXAS,

Concho

County.

Survey No. _____

FIELD NOTES of a Survey of _____

Land made for _____


*M. A. Wistcutt, agent for
The N. T. & G. R. Co. making
connection between Block 10
N. T. & G. R. Co. and the Kichapoo
Creek Survey.*

Said Survey is No. _____ in _____ County, Texas,

situated on the waters of _____, a tributary

of _____ River, about _____

miles _____ of _____



SCALE _____

VARAS PER INCH _____

VARIATION _____

9° 2' E.

Beginning at _____

*N. W. Cor of Sur 24. Blk 10 N. T. & G. R. Co. a S. W. 4 Beamings
Thence South 647 ns. — Thence West 1340 ns the N. E. Cor of
German Emigration Sur No 621 a S. W. and a msg Stamp bearing
N 15 E. 19 ns. this tree was standing three months ago and was well
marked with an old cross and hacks. Since cut down.*

Thence N 55 West 3:0 ns. an old S. W. S. E. Cor G. E. Sur No 620

Thence N 35 E 2850 ns for N. E. Cor G. E. Sur No 618

Thence North 950 ns for N. E. Cor Sur 617.

*Thence N 35 E. at 1344 ns should be N. E. Cor 616, at 1460 found
an old marker \bar{x} msg 10 in dia which bears S 30 E 54 ns.*

*Thence S 55 E 200 ns. — Thence N 35 E 950 ns. (this cor should have
an Elm bearing and the course & distance fell short of an Elm growth
about 30 ns.)*

*Thence S 55 E 470 ns. — Thence N 35 E 1900 ns for N. E. Cor of Sur 614. (Had
I not made an off set to the E I would have run into a bend
of Kichapoo Creek.)*

Thence North (at 950 ns should be N. E. Cor of Sur 613.) 1012 ns.

*Thence East at 174 ns. the N. E. Cor of 613. from which a msg 6 in
dia bns N 1 W 10 ns another 6 in dia bns N 18 W 18 ns. (both old markers &
easily to be seen.*

*Thence East 240 ns. two msg Stumps, one 12 in dia bns N 56 W 5 ns
another 6 in dia bns S 62 W 17 ns. — Thence East 346 ns. W line Sur 14. N. T. & G. R. Co.
Blk 10 — Thence North 604 ns. N. W. Cor Sur 14 Blk 10 N. T. & G. R. Co. S. W. 4 Beamings
to the place of beginning.*

Bearings marked _____

Surveyed _____ 188 _____

Miles Edwards

Hurray Keall

CHAIN CARRIERS.

I, _____

J. W. Ratchford

County Surveyor of _____

Concho

County, Texas, do hereby

certify that the foregoing described Survey was actually made by me on the ground, according to law, on the date and with the Chain Carriers aforesaid, duly qualified, and that all the Corners, Lines, Boundaries and Marks of the same, whether natural or artificial, are truly and correctly described and set forth in the foregoing Plat and Field Notes.

By _____

Deputy.

J. W. Ratchford

County Surveyor.

Concho

County, Texas.

Filed for Record the _____ day of _____ 188 _____, at _____ o'clock _____ M.

Surveyor.

N 1

Counter 19136