

Field Notes of a Survey to determine  
the positions of surveys 30 and 30 Block  
28 of and G. T. R. R. Co. surveys Crosby Co.  
Texas

Originally surveyed 1873 at Declination of  $10^{\circ}45' E.$

(A) Beginning at a rock monument the N.W. corner  
sy 141 of and G. T. R. R. Co. surveys Block 2.  
Then  $\angle$  East at 620 yards cross White River  
continuing East 1900.1 yards to N. W. corner 140  
Block 9. Then  $\angle$  E. 1900.1 yards to the N.E.  
cor. sy 140 Block 9. in hill. Then  $\angle$  North 1900.  
yards to the N.E. cor. sy 144 Block 9. and  
N.W. cor. sy G. H. and G. T. R. R. Co. sy  
Block 28

Variation originally  $12^{\circ} E.$

(B) Beginning at N.W. corner sy 3. aforesaid  
Then  $\angle$  North 1900 yards to N.E. corner  
sy 4 Block 28. Then  $\angle$  North 1900.1 ns.  
to N.E. corner sy 13. Block 28. Then  $\angle$   
North 1900.1 ns. to N.E. corner sy 19 and  
S.E. corner sy 30, a pile of rocks near foot  
of Glazier. Then  $\angle$  West 1900.1 ns. to N.W. corner  
sy 30, a pile of rocks in mesquite flat  
Then  $\angle$  North 1900.1 yards to N.W. corner sy  
30 aforesaid a pile of rocks in North  
side of draw near cottonwood wood.  
Then  $\angle$  E. at about 1800 ns edge of plain  
continuing E. 1900.1 ns a stake in plain  
N.E. corner sy 30. Then  $\angle$  off plain 1900.  
counter 20011

$$\begin{array}{r} 5900 \\ 1147 \\ \hline 6843 \end{array}$$

verso to D. E. Conner by G. A. Townsend, a pub  
cap rock near foot of Glain<sup>o</sup>

I R. P. Smyth, Clerk. Dy. Crosby  
Land Dist. do hereby certify that the  
foregoing survey was made on the ground  
according to law and that the marks  
natural and artificial are truly described  
herein, and that said survey to H.  
and G. m. R. R. Co. Bkt. 28 does not  
contain or front upon any water.

R. P. Smyth

I H. C. Knight, Dist. Surveyor, Crosby Land Dist.  
do hereby certify that I have examined the foregoing  
plot and field notes and find them correct and  
that they are recorded in my office, in book 2  
page 476

Aug 27<sup>th</sup> 1887

H. C. Knight  
Dist. Surveyor Crosby Ld Dist

(C) Beginning at N.W. corner sy So. Hand & Co.  
R.R. Co. surveys Block 28, a pile of  
rocks on North side of road near  
Cattawissa road (which said corner will  
established from S.W. c. 1/4 mile E. - see  
field note designated (A) and (B) corners  
admitted)

Then N.W. 1/4 ad. vs to M. Co. 2d. Rec  
28. Then N.E. 1/4 ad. vs. to N.W.  
corner sy 27 Rec 28.

Then North ad 6849 varad stake cap  
wok of plumb, continuing North on all  
11400 (compls) to S.W. corner sy So Rec  
28. on plumb. Then North 1900. vs  
to M. Co. said So. Then East 1900.8  
varad to N.E. c. sy So. Rec 28. Then  
South 1900.8 vs. to S.E. corner sy So.  
Then West 1900.6 vs. to N.W. corner 60  
Hand & Co. R.R. Co. Rec 28. (Catfish C.  
on N.E. River to Medwood about 2 miles

I R. Smyth dep't. by Crosby Land Dist.  
do hereby certify that the foregoing  
survey was made on the ground according  
to law, and that the marks natural and


artificial or truly described herein, and  
that said survey of H & G M.R.R. Co. Blk  
28 does not contain or front upon any  
water

R. P. Murphy

I, H C Knight, Surveyor Ousby Land Dist, hereby certify  
that I have examined the foregoing plat and field-  
notes, and find them correct, and that they are re-  
corded in my office in Book 2, page 477.

Aug 27<sup>th</sup> 1887.

H C Knight  
Dist. Surveyor, Ousby Land Dist.



64

Counter 20015

File: 10.

Crosby Co  
Report & Sketch  
from

Dept. Augia Crosby Co.

Showing that

Dech 30 } H. 49.  
Sec. 50 } N. R. R.  
Aug.

do not contain a  
front or any water

Filed in the General Land Office

Octob. 5<sup>th</sup> 1887.

R. A. Shedd  
Chief Clerk.

See State Surveyor's report  
file 11.

15981  
16152  
17228

L. K. John & Son.

Counter 20016

65