

filed 1/23/03 -

Dickens County Texas.

Connecting line from S.W. corner of survey No. 1. cert 97- C. E. P. I. + W. Co. Begin at a stone mound the original S.W. corner of said survey - Thence North 9500 vs. to an iron pipe the N.W. corner of No. 10. Cert. 231- J. W. Dr. S. R. R. Co. end in the East line No. 7. J. W. Dr. S. 986 vs. North of its S. E. corner - Thence East at 1900 vs. pass an iron pipe the N.E. corner of said No. 10. - at 3800 vs. an iron pipe the N.E. corner of No. 4- C. + W. R. R. Co. cert. 67- at 5700 vs. an iron pipe the N.E. corner of a survey in name of T. + G. N. Ry. Co. cert. 527 - Thence South 1900 vs. an iron pipe the S.E. corner of said T + G N Co. + 527

Thence South 227 vs. a point - Thence S. 88 1/2 W. 1459 vs. a point. Thence North 28 vs. to a stone marked N.W. 41 and intended for N.W. corner of survey 41 - Shock and Arnold - as located by some one - but I find it out of position - Begin at this stone - Thence North 197 vs. Thence East 377 vs. the correct N.W. corner of 41 - This as shown by my map places the Survey 41 in conflict with T + G N. R. R. Co.

Sur - cert. 520. - Surveyed Oct. 14, 1902 -
Bearings marked }
Va. 10. 30 E. } Richard Kerney } chain
Alvin Crawford } men

R. W. Kerney State Surveyor

The State of Texas }
County of Dickens } I Jno A Green County Surveyor of Dickens County
do hereby certify that the above connecting line has been duly
recorded in my office in Book 7 Private Survey Records page 40
This the 17th day of July 1902
Jno A Green
Dickens Co Texas