

Filed July 15, 1900
 Dated July 11, 1900
 Crosby Co.

Filed in Genl Land Office
 7/15/1900
 Wise

Surveys surrounding Duffy's Peak

See connecting line by surveyor German



The above sketch shows the position of Duffy's Peak with surveys surrounding as I found them by actual survey on the ground (See my statement filed in Ld office by hands of J.T. Lofton -)

The connection I have made with Block 8. H.V.B.N. R.R. Co. is in accordance with a survey made by W.E. Kaye and Shephard 1887.

The red lines show position of the surveys, as they would be on the ground if Mr W.C. Knight was correct in his location of the NE corner of 1111 J.T. from Duffy's peak, but then the length of the north line of 1111 would be only 1630 varas, and to reach the N.W. corner, 1111 - as established on the ground and which I found, as indicated on this sketch, the course would be $N 83 \frac{1}{4}^{\circ} W 1630$ as. However some difference might be made by his having taken a point farther north ^{and east} than I did at Duffy's peak - I undoubtedly found the monuments as made by Mr Hays, and the N.E. corner of surveys 1110 - 1109, 1111, J.T. and the monument 2015 E of NE 1111, as indicated are all in a direct line

4

Snyder Scurry Co. July 11th 1900 -

F.M. German County Surveyor
 Scurry Co. Land Dist.

Counter 27013

Filed in Real Land Office
11/10/1900

Sketch File # 6 C
Garza Co.

Dated July 16, 1900 -
Filed July 15, 1900.

Surveys Surrounding Dut-
ty's Peak.

4

Counter 24012

