

State of Texas: }
County of Jack: }

In surveying ^{and}
correcting Block B. 2. in Gray
County, Texas, made for the
H. & G. N. R. R. Co. I first
found the N. E. corner of survey
No. 1, Block No. 2, made for
the I & G. N. R. R. Co.

This corner Mr. Spiller failed to
find in his corrections of 1882.
I also found all the original
monuments on the N. line of
Block, No. 2.

As the said N. E. corner of Survey
No. 1, Blk. No. 2, is the control-
ling corner of all these locations
{to wit- Block No. 2, 3, & B. 2.}
I ran out Blk. No. 2, according
to the original field-notes, also
Blk. No. 3.

Then I began at the Monu-
-ment, the S. E. corner of Survey
No. 12, Blk. 3, and surveyed
Survey No. 1, Blk. B. 2. on the
ground, as per original
field-notes & calls; also
Survey No. 2, same block.

Then running out Survey No. 3. by its original calls, I failed to find the monument called for at the S. E. corner, in the original field-notes;

I found however a monument with only one bearing tree which Spiller supposed to be the original monument in his corrections of 1852. But as this monument was 2053 varas too far North, and 721 vs. too far West - it was evidently an error, and I abandoned it, and established monuments in accordance with the original fieldnotes, because it was impossible to reach the old md. by the field-notes.

In my survey I used a heavy Surveyor's transit; (Surrey's Instrument), and kept a system of double fallies, in counting the varas. Thus making a mistake in the survey almost impossible.

April 10th 1885.

J. M. Cretcher

Deputy Surveyor
Jack L. Distr.

Gray County

Statement of
Surveyor.

Filed April 28th 1885.

D. W. Robinson
Chf. Clk.

2