

RECEIVED

119

D'Hanis, Texas; 6/15/31. JUN 17 1931

Hon. J. H. Walker,
Commissioner General Land Office, REFERRED TO MAP
Austin, Texas.

Dear Mr. Walker:

Herewith field notes and plat showing true location of survey lines along south boundary lines of T. C. Ry. Co. surveys Nos. 1037, 1038, 1043 and 1066 on the north, and north boundary lines of surveys Nos. 850.2, 850.3, 852, 853, 1070, 854, 854.5, 891, 260 & 861.

In answer to my letter of September 29th, 1930, asking for interpretation and opinion of the General Land Office relative to the south boundary lines of the T.C.Ry. Co. Surveys, including survey Nos. 1037, 1038, 1043 and 1066, you stated that after a careful study of the surveys in question, you concluded that the west line of survey No. 1066, should go its distance of 1900 vrs. south from the S. W. corner of survey No. 1065, as established by be add explained in said letter of September 29th, 1930.

The accompanying plat will show the result of placing this south boundary line of 1066 243 vrs. further south than the south line of survey No. 1043. If it is still your opinion that the south line of survey No. 1066 should be 1900 vrs. south of the south line of 1065, thereby cutting into two parcels the Micthurson survey and taking parts of surveys Nos. 854.5 854 and 853, kindly advise accordingly and if field notes drawn to correspond with this line are to replace those sent herewith, insofar as they effect the Micthurson and the H. I. Christman surveys.

If on the other hand the opinion should prevail that the field notes as drawn should stand, I would thank you for their return to me for signature, seal and recording in Surveyors' records in Uvalde and Real counties.

As to original field notes of survey No. 1038 calling at its S. W. corner for rock mound on high mountain, beg to say that the S.E. corner of this survey is on top of a mountain, then going west along south line 1038 a valley is crossed at about 750 vrs then the upper edge of another mtn. and its distance call of 1498 vrs. terminates near a creek at the lower edge of this latter mtn. Then continuing west along this line another wide valley is crossed, possibly another 600 vrs wide. This eliminates all possibility of the S. W. corner of survey No. 1038 being on top of high mountain. It is unquestionably a call in error, by the surveyor who drafted the field notes in question.

Thanking you in advance for your reply to this communication, beg to remain,

Very truly,

Arthur H. Roche

See Watkins
report in S-48762
Sub division field
notes of 1066.
55989, 56035,
85791, 97801
124452 -

7-8-31

Handwritten signature or name at the top of the page.

Handwritten number '4-8-51' in the upper left corner.

Top section of the document containing several lines of faint, mostly illegible text.

Middle section of the document with faint text and a large handwritten number '1780' written over the lines.

Handwritten numbers '656' and '646' written across the middle section of the document.

Bottom section of the document containing faint text, possibly a signature or official stamp.

D'Hanis, Texas; 7/16/31.

Col. J. H. Walker,
Comm. General Land Office,
Austin, Texas.

Dear Sir:

In connection with a resurvey of various surveys in the extreme southeast corner of Real county, Texas, beg to submit the following data:

I located on the ground the original S. E. corner survey NO. 1037, with bearing a L. O. now 24" dia. N. 25 E. 27 vrs. standing and plainly marked; an old fence corner at point S. 25 W. 27 vrs. from brg. tree.

Thence went to S. E. corner of survey No. 850.2. Here found cedar 15" dia. S. 84 E. 26.5 vrs. plainly marked; W. O. N. 45 W. $2\frac{1}{3}$ vrs. rotted out, - various other white oaks here. This corner is on east slope of hill about 75 vrs. from bottom of deep creek. Thence run line north 1087 vrs., found nothing, this distance terminating nine vrs. south of the original S. E. corner survey No. 1037, T. C. Ry. Co.

Thence run line west and at 1244 (corrected by measure former distance of 1260 vrs. as set out in letter of 9/29/30.) found stone mound and cedar 8" dia. W. 8 vrs. Do. 6" S. 64-30' E. 7.5 vrs. (both trees standing) continuing line west I located S. W. corner survey No. 1037, 1830 vrs. west of its S. E. corner, a rk. md. on top of mountain fr. wh. a Pin Oak, now dead, (two young trees grown up from old stump, N. 81 E. $\frac{1}{2}$ 6.4 vrs. all bark fallen from dead tree and no marks distinguishable. From this rk. md. north I located four hacked line trees indicating original west boundary line of survey No. 1037.

Continuing west along south line 1038 located N. W. corner survey No. 852, ^{7/8} PIN OAK 12" dia. S. 88-30' E. 7.4 vrs. & cedar 12" S. 21-45' W. 19 vrs., both trees standing.

Beginning at S. E. corner survey 615 a rk. md. - a cedar 7" brs. N. 65 E. 37.3 vrs. Do. 10" dia. brs. S. 86 E. 37.2 vrs. both trees alive. Thence N. 16 W. 2688 vrs., found nothing; thence S. 74 W. 374 vrs. found nothing, Thence N. 16 W. 448 vrs. for N. E. corner survey No. 853, found nothing.

Beginning at N. E. corner survey No. 861, Whitlock, a rk. md. on E. bank of cherry creek P. O. 4" brs. S. 82-45' E. $1\frac{3}{5}$ vrs. Do. 4" brs. S. 26-45' W. 4 vrs. (both trees standing) thence south 950 vrs. found nothing; thence west 240 vrs. found nothing; thence south 87 vrs. for S. W. & N. W. cor. resp. surveys 1065 & 1066, -found nothing. set stake and mound of rocks for corner and marked bearings L. O. 16" S. 67 E. 10.5 vrs. and L. O. 16" dia. S. 50 E. 19 vrs. thence south 1900 vrs. to rk. md. for S. W. corner 1066, thence east 1900 vrs. to rk. md. for S. E. corner 1066, thence north 243 vrs. to S. W. corner survey No. 1043 and N. W. cor. No. 1070 Michurson. Proceeded to run lines of surveys as per field notes herewith.

Very truly yours,

Arthur A. Rathe.

counter 35057

Sketch file No. 7
Harris Co. Survey
Comm. General Land Office
Austin, Texas
Filed January 24, 1931

Sketch File No. 7

Real Co County
Arthur H. Rothes Report
Surreys in S.E. Part of County
Filed August 3rd, 1931

J. H. Walker, Comm.

C. F. Plunket

File Clerk

Descriptive: See accompanying
report - File #6.

See Sk & Report filed 9/8/31.

" " " " 4/18/32

Field notes accompanying these
returned to S. J. White.

Benef. SK. 10, Box 3-41327

notes herewith.
Michelson. Proceeded to run lines of surveys as per field
ars. to S. W. corner survey No. 1043 and N. W. cor. No. 1020
1900 ars. to rk. mq. for S. E. corner 1066, thence north S44
south 1900 ars. to rk. mq. for S. W. corner 1066, thence east
67 E. 10.5 ars. and l. 0. 18" dis. S. 50 E. 19 ars. thence
mound of rocks for corner and marked bearings l. 0. 18" S.
cor. resp. surveys 1066 & 1066 - found nothing. set stake and
ars. found nothing; thence south 87 ars. for S. W. & N. W.
ing) thence south 930 ars. found nothing; thence west 240
l 3/8 ars. D9. 4" prs. S. 28-45, W. 4 ars. (both trees stand-
rk. mq. on E. bank of cherry creek P. O. 4" prs. S. 85-45, E.
Beginning at N. E. corner survey No. 891, Whitlock, &

W. 448 ars. for N. E. corner survey No. 823, found nothing.
nothing; thence S. 74 W. 347 ars. found nothing. thence N. 18
27.5 ars. both trees alive. thence N. 18 W. 288 ars. found
cedar 7" prs. N. 65 E. 77.5 ars. Do. 10" dis. prs. S. 86 E.
ars. & cedar 18" S. 28-45, W. 19 ars. both trees standing.
corner survey No. 823, E. corner survey 615 & rk. mq. - S
OAK 18" dis. S. 88-30 W. E. 7.4

Beginning at
ars. & cedar 18" S. 28-45, W. 19 ars. both trees standing.
corner survey No. 823, E. corner survey 615 & rk. mq. - S
OAK 18" dis. S. 88-30 W. E. 7.4
ars. & cedar 18" S. 28-45, W. 19 ars. both trees standing.
corner survey No. 823, E. corner survey 615 & rk. mq. - S
OAK 18" dis. S. 88-30 W. E. 7.4

Beginning at
ars. & cedar 18" S. 28-45, W. 19 ars. both trees standing.
corner survey No. 823, E. corner survey 615 & rk. mq. - S
OAK 18" dis. S. 88-30 W. E. 7.4
ars. & cedar 18" S. 28-45, W. 19 ars. both trees standing.
corner survey No. 823, E. corner survey 615 & rk. mq. - S
OAK 18" dis. S. 88-30 W. E. 7.4

Beginning at
ars. & cedar 18" S. 28-45, W. 19 ars. both trees standing.
corner survey No. 823, E. corner survey 615 & rk. mq. - S
OAK 18" dis. S. 88-30 W. E. 7.4
ars. & cedar 18" S. 28-45, W. 19 ars. both trees standing.
corner survey No. 823, E. corner survey 615 & rk. mq. - S
OAK 18" dis. S. 88-30 W. E. 7.4

Beginning at
ars. & cedar 18" S. 28-45, W. 19 ars. both trees standing.
corner survey No. 823, E. corner survey 615 & rk. mq. - S
OAK 18" dis. S. 88-30 W. E. 7.4
ars. & cedar 18" S. 28-45, W. 19 ars. both trees standing.
corner survey No. 823, E. corner survey 615 & rk. mq. - S
OAK 18" dis. S. 88-30 W. E. 7.4

Beginning at
ars. & cedar 18" S. 28-45, W. 19 ars. both trees standing.
corner survey No. 823, E. corner survey 615 & rk. mq. - S
OAK 18" dis. S. 88-30 W. E. 7.4
ars. & cedar 18" S. 28-45, W. 19 ars. both trees standing.
corner survey No. 823, E. corner survey 615 & rk. mq. - S
OAK 18" dis. S. 88-30 W. E. 7.4

Very truly yours,
Arthur H. Rothes

Dear Sir:
Austin, Texas.
Comm. General Land Office,
Col. J. H. Walker.

D. Harris, Texas; 7/16/31.

counter 35058