

329

RECEIVED

SEP 8 - 1931

REFERRED TO MAP

D'Hanis, Texas; 9/4/31.

Hon. J. H. Walker,
Comm. General Land Office,
Austin, Texas.

Dear Sir: Answering requests in copy of General Land Office letter to Mr. S. J. White of Leakey, Texas, dated August 7th, 1931, beg to submit further data on location and marks of original corners identified on surveys lying along Real-Uvalde county line as follows:

The L. O. brg. called for as witness to S. E. corner survey No. 1037 is marked X.

The Cedar 15" dia. a witness tree to S. E. corner survey No. 850.2, as described in field notes of Mr. J. Chism in survey made by him on Oct. 16th, 1911, is marked X. The 5" white oak called for here is dead and fallen with no marks visible. The witness trees found at N. W. corner survey No. 850.2, a cedar 8" W. 8 vrs. Do. 6" S. 64-30' E. 7.5 vrs. are marked X, and stand true to call in field notes. See fourth paragraph of Letter to General Land Office dated 7/16/31 describing S. W. corner of survey No. 1037. The corner there described can be no other than the original S.W. corner of survey No. 1037.

The N. W. corner survey No. 852 calls for two witness trees, a Pin oak 12" S. 88-30' E. 7.4 vrs. and a Cedar 12" S. 21-45' W. 19 vrs. Both trees are marked X and stand true to their call.

Witness trees for the N. E. corner of survey No. 861, Whitlock, P. O. 4" S. 82-45' E. 1.6 vrs. and do, 4" S. 26-45' W. 4 vrs. Both trees marked O and stand true to call.

In connection with field work of August 16th to 21st. following instructions of General Land Office letter of August 7th to S. J. White, a copy of which was sent to my address, the following data: I checked again the south lines of surveys Nos. 1037 and 1038 with no change in results. Running north from rock mound, the S.W. corner No. 1038 as determined on previous surveying, I located rk. md. and fence corner 1900 vrs. north; this point being 80 vrs. N.

of the center of ~~Cherry~~ Blanket creek for N. E. corner survey No. 1043, at 2418 vrs. found rk. md. in deep ravine, a short steep header leading into Blanket creek. This fits the call in field notes for S. W. corner survey No. 1040. From this rk. md. I ran a line north which line follows the bed of Blanket creek, upstream, for 800 vrs. then crosses divide, and at 1040 enters short drain leading into main drain, a tributary of the Sabinal River.

Set up over rk. md. the original S. W. corner of survey No. 615. Here found SP. Oak 4" N. 50 W. 7.2 vrs. mkd. X and Sp. O. 3" N. 54 W. 9.2 vrs. (tree dead and fallen) Thence ran line north 16 degrees west 2688 vrs. to stake and rk. md. for N. W. corner and S. W. corner survey No. 853; thence N. 74 E. at 1061, west bank of Blanket creek, at 1344 vrs. -- bearing trees called for here as designation point on south line of survey No. 853 are gone, there being a field in cultivation at this point, at 1811 vrs. W. bank of creek or drain. The call on south line 853, viz: "at 1838 enter branch, at 1888 E. bank of creek, at 1918 crossed branch again."

a

counter 35059

can be accurately located along this line, but will cause conflict with survey No. 615 by about 75 yrs.

Also ran line N. 74 E. from S. W. corner No. 615 as above described and at 1369 yrs. found rk. md., the N. E. and N. W. corner of surveys Nos. 235 and 237 respectively, fr. wh. a Cedar 10" dia. brs. S. 86 E. 37.2 yrs. and a L. O. 18" dia. brs. N. 43-30' E. 228 yrs. Both trees marked \bar{X} , continued N. 74 E. and at 2729 yrs. found rk. md. on east slope of hill, the original S. E. corner survey No. 615, a cedar 10" S. 86 E. 37.2 yrs. do. 7" dia. N. 65 E. 37.3 yrs. both trees mkd. \bar{X} and stand true to call. thenceran line N. 16 W. -- bearing trees called for along this line as designation point not found, at 2608 yrs. found rk. md. on north slope of mtn. fr. wh. a cedar 5" brs. S. 19 E. 3.4 yrs. tree mkd. \bar{X} . Pin Oak 8" N. 76 E. 2.2 yrs. now dead and lying on ground. This corner too far south and will conflict by 80 yrs. along north line of 615.

Set up on rk. md. the N. W. corner survey No. 852, -N.1/2- and ran line S. 16 E. intersecting north line of survey No. 615, This line measures 850 yrs. and intersects north line 615 distant, 352 yrs. S. 74 W. from the N. E. corner of survey No. 615.

Beginning at a rk. md. the S. E. corner survey No. 854, in west line survey No. 615, at 232 yrs. pass the N. W. corner of survey No. 615, 1344 yrs, set rk. md. for the N. W. corner of survey No 853 and N. E. corner No. 854. in south line survey No. 853 1/4, Cude. thence south 74 west 1344 yrs. and set rk. md. for N. W. corner 854 and an interior corner of survey No. 854.5.

From N. E. corner survey No. 853 ran line north and interseted at 153 yrs. the south boundary line of survey No. 1066, T. C. Ry. Co.

Located the N. E. corner of survey No. 260 S. E. Felts, a rk. md. in low Mtn. Pass fr. wh. a rk. bluff in head of small ravine brs. S. 29 W. 10 yrs. Sp. O. 10" S. 30.6 yrs. Found bearing tree fallen and rotted marked young tree 8" dia. grown out of old root system S. 30.8 yrs. \bar{X} . Round Mtn. pinnacle brs. S. 12 W. 80 yrs. and the S. W. corner of survey No. 1066 brs. S. 77-5' E. 443 yrs. From this point ran line south 20 west 950 yrs. for S. E. corner survey No. 260 found line to terminate in field and bearings grubbed out. Thence west and at 400 yrs. crossed Cherry creek. At a point in east line survey No. 260, 400 yrs. N. 20 E. from its S. E. corner looked for bearing trees called for in field notes of survey No. 892, but found nothing as fire has destroyed all old timber. Located N. E. corner survey No. 891, a Sp. O. stump on west bank of creek for corner fr. wh. a Sp. O. 10" brs. S. 17 E. 19 yrs. Hull of bearing tree only remaining and a cluster of Saplings grown out of old root system. From said Sp. O. stump on west bank of creek, I ran a line N. 70 W. for north line survey No. 891, and at 581 yrs. intersected east line of survey No. 260 distant 579 yrs. S. 20 W. of its N. E. corner.

From N. E. corner survey No. 891 ran a line S. 20 W. 321 vrs.
and set rk. md. for N. W. corner survey No. 892, thence east
587 vrs. to intersect with west boundary line of survey No. 854,
which point of intersection is distant 435 vrs. S. 16 E. of the
N. W. corner survey No. 854.

Very truly yours,

Arthur S. Roth
Licensed Land Surveyor.

Stamp File No. 9
County
Date
1891

25024-1000-10/10/11-10

Sketch File No. 9.....

Real County

Arthur H. Rath's Report
Sur's. in S.E. Part of County

Filed September 8th 1931.....

J. H. Walker, Comm.

O. H. Blucher

File Clerk

Descriptive:.....

.....

.....

See Sk + Report filed 9/8/31. - #8

Pencil Sk. in Box S. A1327

From N. E. corner survey No. 831
to S. E. corner survey No. 832
to S. E. corner survey No. 833
to S. E. corner survey No. 834
to S. E. corner survey No. 835
to S. E. corner survey No. 836
to S. E. corner survey No. 837
to S. E. corner survey No. 838
to S. E. corner survey No. 839
to S. E. corner survey No. 840
to S. E. corner survey No. 841
to S. E. corner survey No. 842
to S. E. corner survey No. 843
to S. E. corner survey No. 844
to S. E. corner survey No. 845
to S. E. corner survey No. 846
to S. E. corner survey No. 847
to S. E. corner survey No. 848
to S. E. corner survey No. 849
to S. E. corner survey No. 850
to S. E. corner survey No. 851
to S. E. corner survey No. 852
to S. E. corner survey No. 853
to S. E. corner survey No. 854
to S. E. corner survey No. 855
to S. E. corner survey No. 856
to S. E. corner survey No. 857
to S. E. corner survey No. 858
to S. E. corner survey No. 859
to S. E. corner survey No. 860
to S. E. corner survey No. 861
to S. E. corner survey No. 862
to S. E. corner survey No. 863
to S. E. corner survey No. 864
to S. E. corner survey No. 865
to S. E. corner survey No. 866
to S. E. corner survey No. 867
to S. E. corner survey No. 868
to S. E. corner survey No. 869
to S. E. corner survey No. 870
to S. E. corner survey No. 871
to S. E. corner survey No. 872
to S. E. corner survey No. 873
to S. E. corner survey No. 874
to S. E. corner survey No. 875
to S. E. corner survey No. 876
to S. E. corner survey No. 877
to S. E. corner survey No. 878
to S. E. corner survey No. 879
to S. E. corner survey No. 880
to S. E. corner survey No. 881
to S. E. corner survey No. 882
to S. E. corner survey No. 883
to S. E. corner survey No. 884
to S. E. corner survey No. 885
to S. E. corner survey No. 886
to S. E. corner survey No. 887
to S. E. corner survey No. 888
to S. E. corner survey No. 889
to S. E. corner survey No. 890
to S. E. corner survey No. 891
to S. E. corner survey No. 892
to S. E. corner survey No. 893
to S. E. corner survey No. 894
to S. E. corner survey No. 895
to S. E. corner survey No. 896
to S. E. corner survey No. 897
to S. E. corner survey No. 898
to S. E. corner survey No. 899
to S. E. corner survey No. 900

Very faint notes.
Arthur H. Rath
Surveyor

counter 35062