

I, W. T. Hope, County Surveyor of Val Verde County  
hereby certify, that I began at the S. W. cor. of Sec.  
No 45 - Block A2. & st. mid at corner of fence  
from which a cedar 5" bns. S 34 E. 16 ms. (This  
corner was located from a corner at the S.E. corner  
of No 45 - a L.O. S 70 E. 45 ms - a cedar bush S 30 E. 28 ms)  
I then ran North 1900 along fence - Then North 1900  
ms along fence - Then North ~~about~~<sup>strongly</sup> 1500 ms along fence -  
Thence North along fence 950 ms. to corner of fence which is  
the middle of section of Section No 5 - Block A22 -

I then ran East along fence 1900 + 1900 + 1900 + 1900 + 300 ms  
to the East line of Section No. 49 - which is at corner  
of fence - I then ran North 950 ms and to  
300 ms West and looked for a corner as described  
in field notes: a L.O. 12° mtd bns S 63 E 11 ms -  
a L.O. mtd V S 18 E 21 ms, and made a diligent search  
for corner but found none - I then returned to the  
point 300 ms to East - Then ran North 1900 ms - and  
west 300 ms. and found no corner to answer descriptions  
in field notes: namely cedar mtd V N 27 E. 23 ms -  
then returning to point 300 ms. East - I then ran North  
1900 and West 300 ms. and found no corner described  
in field notes: namely cedar mtd N 32 W 72 ms  
then returning to point 300 ms. East - I then ran  
North 1900 ms and West 300 ms - found no corner  
to answer description - namely a L.O. mtd A N 4 E. 17 ms

returning to point 300 m. East I then ran North  
1900' and West 300 m. and found nothing to fit description  
which only calls for a st. and 2 ft. high - returning to the  
point 300 m. to East - I then ran North 1900' and West  
300 m. and found nothing at does not call for any  
description only a rock mound on East edge of ravine  
then returning to point 300 m. East I ran North  
1173 m. to the N.E. corner of No. 50-Block 022  
which is at corner of fence - fence is running West and  
South from this point

---

this is to certify that I began at N.W. cor. of  
Block No. 1 - which corner was made by R.S. Doak a st. and  
into NW 1 BLK 1 - a.s.o. 2" I - 0008 S. 1.0" L. 2" = ne...  
L.O. x N 16° 45' E 2.6 - Then ran South 1900 m. - Then  
west 1900 m. - Then South 1900 + 1900 + 2430 + 727  
m. to fence on the north line of Block 444

W. T. Hope

C. Surveyor Nat'l Grid Co

Del Rio Texas. Feb 18<sup>th</sup> 1933

3372

Hon J. N. Walker Com<sup>t</sup>  
Austin Tex


Dear sir

Dear sir:

I am enclosing sketch with all  
of connections made by me. This is the best paper  
that I can get at the present time. Sketched is under reported  
cover.

Yours truly

W. T. Hope  
Co Surveyor



RECEIVED

FEB 20 1933

REFERRED TO MAP

counter 39242

Del Rio Tex Jan 23 - 1933  
Hon. J. W. Walker Com<sup>r</sup>  
Austin, Texas

3250

Dear sir:

In reply to your letter of the 18<sup>th</sup>  
to Mr. W. P. Wallace - the North line of 4444 was  
established by Ratchford which has a fence on  
line - it is evidently correct - am satisfied  
that the corners in Block 922 are not on ground  
as they have been looked for by different surveyors  
who have not been able to find them - now what do  
you suggest? have done all that I know.

yours truly  
W. T. Stope

RECEIVED

JAN 25 1933

REFERRED TO MAP

counter 39243

Del Rio, Texas, Dec. 15<sup>th</sup>, 1932

2070  
1

Hon. J. H. Walker, Com<sup>e</sup>

RECEIVED

Austin, Texas.

DEC 16 1932

Dear sir:

this letter is written <sup>REFERRED TO MAP</sup> at request of  
Mr. Blecher in straightening up field notes of  
Survey 4 - Mrs. D. Shepper and Survey 42 - Mrs. A. J. Ansley

I began at S. SW. cor. of Survey 7 - Block a 2  
which is well defined cor. a large st. md. with cedar 6"  
N 72° W. 8 mrs. - I then ran East to the S. E. cor. No. 27  
and found a st. md. ther was about 430 mrs. excess  
I then ran north along fence to the N. E. cor. No. 39.  
a large st. md. from which L.O. S 70 E. 45 mrs. -  
a cedar bs S 30 E. 28 mrs. there was 1199 1/2 mrs.  
leaving an excess of 594 mrs. - I then ran west  
1964 mrs. to the S. W. cor. of No. 45 - I then ran North  
along fence 6250 mrs. to the middle of Survey No. 5  
Block a 22. I then ran East 7800 along fence  
and found the East line of No. 48 to be right  
which is on fence - There's North at 950 mrs  
measured West 300 mrs. and found no evidence  
of the N. E. cor. of No. 48 at 2850 mrs. found  
no evidence of corner No. 45 - 300 mrs. to west  
and found no evidence of corners 300 mrs. to West.

and continuing on 11623 west to the N. cor of No 2  
30? 50 and run of the corners as described in  
in the field notes of No 44, 33, 32 and 27 -  
did not measure across surveys 1 and 2. Block 44,  
as it has been measured several times by Surveyors  
I had a fence to measure on the whole distance

W. T. Hope  
Co. Surveyor

Length	Distance	Surveyor	Date
100	100	W. T. Hope, Co. Surveyor	1894
100	100	W. T. Hope, Co. Surveyor	1894
100	100	W. T. Hope, Co. Surveyor	1894
100	100	W. T. Hope, Co. Surveyor	1894

Sketch File No. 31

Val Verde County

W. T. Hopes Statements

Blks V.7 & V.8

Filed 193

J. H. Walker, Comm.

C. F. Blucher

File Clerk

Descriptive:

counter 39246

Del Rio, Texas Mar 22-1922

701<sup>b</sup>

Hon J. H. Walker, Comr  
Austin Texas

Dear Sir:

I am sending connections in reference  
to north line of Block 982 requested in your letter  
of March 11<sup>th</sup>

W. G. Hope

RECEIVED

C. Surveyor

MAR 23 1933

REFERRED TO MAP

counter 39277

3014

W. T. Hope, County Surveyor of Val Verde  
County, hereby certify that I began at the  
sawdust corner at the N.W. cor. of Survey 2670  
I then ran south 5126 ms. - East 1228 ms  
South 2790 ms to the recognized corner of  
of Sur. 3 Mrs. D. Schepker.

W. T. Hope

C. Surveyor

counter 39218