

Checked by  
 J. C. de Hoste  
 June 10, 1881


J. C. de Hoste, Dep't Sur. Palo Pinto Land Dist  
 do hereby certify that the sketch shown on  
 this sheet is correct, and that the lengths  
 of lines shown by red figures are from  
 measurements actually made on the  
 ground.

Ben Austin  
 June 10, 1881

J. C. de Hoste  
 Dep't Sur Palo Pinto  
 Land Dist

I D. Cunningham Surveyor of Palo Pinto Land District -  
 do hereby certify that - I have examined the  
 foregoing sketches and find them correct - as per  
 app to calculation.

Given under my hand at Palo Pinto  
 this June 17<sup>th</sup> 1881  
 D. Cunningham  
 Surveyor Palo Pinto Land Dist



This block was surveyed by measuring the lines  
 S. 87° W. from the flag staff at Fort Concho, for  
 the E. & S. corner of Survey No. 1. The East & North  
 by lines of the block were then run & measured  
 to the N.W. cor of Survey No. 36. Connections were  
 then made with the I.I.T.T. Survey, as shown  
 & with Rodriguez Survey - the S.E. corner of the  
 Rodriguez was found by following its connection  
 from the river & found right for easting, but  
 was 400 or too far north for its call. Both lines are  
 standing & well marked.

This block was surveyed by measuring the lines  
 S. 87° W. from the flag staff at Fort Concho, for  
 the E. & S. corner of Survey No. 1. The East & North  
 by lines of the block were then run & measured  
 to the N.W. cor of Survey No. 36. Connections were  
 then made with the I.I.T.T. Survey, as shown  
 & with Rodriguez Survey - the S.E. corner of the  
 Rodriguez was found by following its connection  
 from the river & found right for easting, but  
 was 400 or too far north for its call. Both lines are  
 standing & well marked.

J. C. de Hoste  
 Dep't Sur Palo Pinto Land Dist

The lines S. 87° W. from Flag staff at Fort Concho  
 Flag staff is in center  
 of Paraded corner of the Post.

